

RETEC 3912



**PHASE I ENVIRONMENTAL SITE ASSESSMENT  
SILVER BAY LOGGING  
121 THROUGH 165 S. RIVER STREET <sup>(1)</sup>  
SEATTLE, WASHINGTON**

Prepared For:

Port of Seattle Engineering Department  
Seattle, Washington

Prepared By:

Onsite Enterprises, Inc.  
6605 - 146 Avenue NE  
Redmond, Washington

January 1998

## CONTENTS

	Page
EXECUTIVE SUMMARY	1
1. INTRODUCTION .....	2
Purpose	
Special Terms and Conditions	
Limitations and Exceptions of Assessment	
Limiting Conditions and Methodology Used	
2. SITE DESCRIPTION .....	2
Location and Legal Description	
Site and Vicinity Characteristics	
Site Structures and Improvements	
Environmental Liens/Other	
Current Uses of the Property	
Past Uses of the Property	
Adjoining Properties	
3. RECORDS REVIEW .....	5
Environmental Records Sources	
Physical Setting	
Historical Use	
Offshore Sediment Quality	
4. INFORMATION FROM SITE RECONNAISSANCE .....	8
Hazardous Substances in Connection with Identified Uses	
Hazardous Substance Containers and Unidentified Substance Containers	
Storage Tanks	
Indications of PCBs	
Indications of Solid Waste Disposal	
Physical Setting/Cross-Media Contamination	
Other Conditions of Concern	
Site Plan	
5. FINDINGS AND CONCLUSIONS .....	11
6. SIGNATURE OF ENVIRONMENTAL PROFESSIONAL .....	13
FIGURES AND TABLES	
REFERENCES	
APPENDICES	

## EXECUTIVE SUMMARY

This report summarizes the methods, information sources and findings of a Phase I Environmental Site Assessment of property located at 121 through 165 S. River Street in Seattle, Washington. This report was prepared on behalf of the Port of Seattle, Seattle, Washington. Exact property parcels included within this assessment are described in Section 2.1.

Based on the sources cited herein and the best professional judgment of the preparing Environmental Professional, this assessment has revealing the following environmental-related issues which may have a direct impact on the maximum beneficial use of the subject property:

1. Potential presence of an underground storage tank (UST) at or near the southeast corner of the metal-frame building located at 129 S. River Street. Other possible underground heating oil tanks as may have been associated with residences at 127, 161 and 165 S. River Street (unconfirmed).
2. Past history of boat fabricating and boat storage/refurbishing which could result in the presence of elevated metal concentrations in surface soil (unconfirmed).
3. Possible asbestos-containing acoustical ceiling tile in the office areas of Section A of the building at 121 S. River Street (unconfirmed).
4. Possible PCB-containing ballasts in mercury vapor and fluorescent light fixtures located in both buildings on the property (unconfirmed).
5. Containers (mostly small) of regulated or potentially-regulated materials (polane paints, gasoline, oil, solvents, glues, etc.) at various locations within the two buildings.
6. The use of the property listed at 127 S. River Street (and probably including 129 S. River St.) for a period of up to 5 years (1978 through 1982) by a company (or companies) known as "Waste Systems International" and "Environmental Emergency Services". Although no above-ground evidence of this use remains, there is potential for soil or subsurface contamination arising from improper storage or accidental spillage that may have resulted from this type of historical use (unconfirmed).
7. Presence of contaminants (arsenic, lead, copper, zinc, PCBs and PAH) reported by other investigators in the submerged sediment of Slip No. 3 adjoining the Duwamish River; many of which are in concentrations exceeding state sediment quality standards.

Items 1 through 6 should be evaluated further (Phase II evaluation) using established exploratory or testing methods to determine if UST's are present, and to check for potential soil contaminants and other regulated materials listed above that may be present on site. If UST's are determined to be present at the site, then appropriate measures should be taken to report their presence to the State (Department of Ecology), remove them and check for any releases of petroleum products that may be attributed to past or present leakage. The containers of regulated materials are confirmed as being present on site, but will likely be removed by the current tenants. One exception may be the materials observed in the metal-frame building at 129 S. River Street which is presently unoccupied. Sediment contamination in the adjacent Slip No. 3 is a concern to the extent ownership of the subject parcels extends into submerged lands as so indicated in the legal description.



## **1. INTRODUCTION**

### **1.1 Purpose**

The purpose of this Phase I Environmental Site Assessment is to identify, the extent feasible pursuant to the processes described in ASTM Standard Practice E1527, recognized environmental conditions in connection with the property. The term recognized environmental conditions means the presence or likely presence of any hazardous substances or petroleum products on a property under conditions that indicate an existing release, a past release, or a material threat of a release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water of the property. The term includes hazardous substances or petroleum products even under conditions in compliance with laws. The term is not intended to include de minimis conditions that generally do not present a material risk of harm to public health or the environment that generally would not be subject of an enforcement action if brought to the attention of appropriate government agencies.

### **1.2 Special Terms and Conditions**

The observations and conclusions included in this report are based solely upon the cited sources. Onsite Enterprises, Inc. and the preparing professional are not responsible for identifying any environmental issues not included in these sources or beyond the scope of Phase I Assessments as defined in ASTM Standard Practice E 1527.

### **1.3 Limitations and Exceptions of Assessment**

The methods, sources, findings and conclusions of this Phase I site assessment are applicable solely to the property identified in Section 2. Use of this assessment for adjacent or neighboring properties, or any other properties, is not allowed. This assessment is considered to be viable 180 days from the date of preparation.

### **1.4 Limiting Conditions and Methodology Used**

No environmental site assessment can wholly eliminate uncertainty regarding the potential for recognized environmental conditions in connection with the property. Performance of this assessment in compliance with established practices (ASTM Practice E 1527) is intended to reduce, but not entirely eliminate, uncertainty regarding the presence of such conditions. No warranties or guarantees are expressly made or implied regarding the absence or presence of such conditions. This assessment may not identify environmental conditions created or exposed at the site as the result of subsequent site development or site uses, including buried articles or waste not identified in cited sources or without surface expression (i.e., readily visible during non-intrusive site inspection) or articles or wastes brought onto the site after the date of the site inspection and not included in the inspector's log and photographs.

## **2. SITE DESCRIPTION**

### **2.1 Location and Legal Description**

The property included in this Phase I assessment is situated in the City of Seattle, in the County of King, in the State of Washington at approximate latitude 47° 32' 34" N and longitude 122° 19'

57" E at the north side of Slip No. 3 on the east shore of the Duwamish River (Figure 2.1). The parcels are shown in Figure 2.2 and are described as follows:

Lots 16 through 22, Block 10, Joseph R. McLaughlin's Water Front Addition to the City of Seattle, according to the plat thereof recorded in Volume 13 of Plats, Page 28, Records of King County, Washington;

And that property which lies southerly of the southerly boundary of lots 16 through 22, Block 30, Joseph R. McLaughlin's Water Front Addition to the City of Seattle, according to the plat thereof recorded in Volume 13 of Plats, Page 28, records of King County, Washington, northerly of the southerly boundary of that certain tract conveyed to Louis De Mattea and Natheale De Mattea, his wife, by deed executed by Pacific Construction Company and recorded under recording No. 7301240233, records of King County, Washington, westerly of the southerly production of the easterly line of said lot 16 and easterly of the southerly production of the westerly line of said lot 22.

Situated in the County of King, State of Washington.

## 2.2 Site and Vicinity Characteristics

The site consists of mostly level shoreline land at the north side of Slip No. 3 off the Duwamish River. The site is fenced and contains two buildings at 121 and 129 S. River Street. The upland area, approximately 280+ ft wide and 140(  $\pm$  ) ft deep is on the south side of River Street. The shore of the property contains a treated-wood quay (approx. 40-ft wide) extending the length of the shoreline and built out over the shoreline rip-rap to serve as a moorage wharf for barges and medium-sized vessels. The general vicinity is characterized by marine and non-marine-related industrial activities, including a railroad bed at the property's north side, a fueling dock and cold storage facility (SCS Cold Storage) to the east, and the Muckleshoot river access to the immediate west. A medium-sized ship yard (former Marine Power) is operated at the south shore of Slip No. 3 (across the slip from the subject property) and currently houses several tenants.

## 2.3 Site Structures and Improvements

The site is fenced with an entry gate opening into the central portion of the property near the north east corner of the "Front Office Building" at 121 S. River Street. The site contains two buildings; the aforementioned office building and a metal-frame "Warehouse" at 129 S. River Street. Another structure, referred to as a "house" was formerly located between the two existing structures (Figure 2.3) but has since been removed. The office building at 121 S. River Street is comprised of the original Section A: a single-story concrete-masonry-block building (40 ft x 80 ft) and a metal-frame addition (Section B) on the south end (toward Slip 3). The warehouse is comprised of a single-story metal-frame building. Both buildings contain interior rooms (mostly wood fabricated) including small offices, storage areas and machine shop. The shore of the property contains a treated-wood quay (approx. 40-ft wide) extending the length of the shoreline and built out over the shoreline rip-rap to serve as a moorage wharf for barges and medium-sized vessels.

## 2.4 Environmental Liens/Other

No information was encountered during the course of this assessment indicating the existence or potential for an environmental lien upon the subject property. However, this should be confirmed through the formal title search process.

## 2.5 Current Uses of the Property

A site reconnaissance was conducted on January 7, 1998. Photographs taken during the reconnaissance are included in Appendix A. Observed current uses of the property include the following:

### Warehouse:

currently vacant - miscellaneous storage.

### Front Office Building - Section A

current tenant: Skywalker Industrial - development and research of marine propulsion systems. Boat storage, engine overhaul, machine shop, offices.

### Front Office Building - Section B

current tenant: self-employed carpenter - wood product fabrication, office furniture fabrication.

### Dock:

Barge moorage, minor overhaul, small vessel haul-out (a mobile crane is located on the dock).

### Yard:

Parking, Storage - miscellaneous equipment, vessels, fishing floats, tires.

## 2.6 Past Uses of the Property

A review of historical aerial photographs (Appendix B) available for certain years ranging from 1936 to 1995 at Walker and Associates, Inc. (Seattle) indicated the first development to be a small shingle mill, sawdust burner and three residences (single-family units) at the site in 1946 (Figure 2.4). One residence is located just north of the shingle mill, and the other two are on parcels at the extreme east of the site (161 and 165 or 167 S. River Street). All of these structures were confirmed by the 1949 Sanborn Map (Figure 2.5). The 1956 aerial photograph confirms the presence of the residence at 127 S. River Street and the grading for the foundation at 121 S. River. The 1960 aerial photograph shows the presence of Section A of the front office building. The 1966 Sanborn Map (Figure 2.6) shows the residence at 127 S. River and Section A of the 121 S. River building labeled "Contractor's Shop" with a small storage building to the south. No other structures are present (the residences at 161 and 165 S. River are gone). Small boat buildings are shown on the property to the west. The 1969 aerial photograph shows the presence of Section B of the front office building and the large cold storage building on the north shore of slip 3 to the east. The aerial photo from 1974 (Figure 2.7) shows the site in its approximate current configuration-except the residence at 127 S. River can still be seen. Other aerial photographs (see summary in Appendix B) show the site under various use conditions with logs and miscellaneous material

stored in the yard. The 1985 aerial photo, as well as the Port of Seattle map from 1986 (Figure 2.8) shows an additional building on the premises immediately south of the one at 129 S. River St. The purpose or use of this building is unknown and it has since been removed. The residence at 127 S. River is observed in the 1990 aerial photograph, but is absent in the 1995 photograph.

A search of historical city directories (R.L. Polk and Cole) provided a historical overview of the occupants of the structures at and near the site (Table 2.1). The first listing for the 121 address is for 1958 and includes Pacific Construction Company (excavating contractors) up until 1963 when the listing becomes "Pacific Paving Company - Road Contractors". Pacific Paving occupied the building until 1978. After that date, various marine-related tenants are listed (Morton Marine, Work Boats Northwest, Reagan Marine Services). For the 127 address, there is an early listing for the South Seattle Shingle Co. (later the Cascade Shake & Shingle Co.) for the years 1948 through 1951. There are no subsequent listings for the 127 address (and possibly pertaining to the 129 address as well, since no listing for that street number is provided separately) until 1961; with the building(s) being occupied by "Stanley Enterprises - Manufacturer's Agents". Other occupants present over the period of 1965 through 1977 are listed in Table 2.1. For the period beginning in 1978, and possibly extending up to 1983, the building tenants included a firm (or firms) listed as "Waste Systems International - Ecology Consultants" (1978) and "Environmental Emergency Services" (1980). The next listing (1983) shows the building(s) to be vacant. The directory search also confirms the approximate period of the residences observed at the east side of the site. Listings for these residences extend through 1955 and are discontinued thereafter. Occupants at the 150 S. River Street address (across the street from the site) are also listed (Mitchell Bros. Truck Line, and Van Dyke Trucking, Inc. - the current occupant).

During the site reconnaissance, the current owner representative indicated that the warehouse building (129 S. River) was formerly occupied by a small metal boat fabricator (Workboats Northwest) and was also used by the State Fisheries Department for vessel storage.

## 2.7 Adjoining Properties

Adjoining properties include the Muckleshoot's Duwamish River access site on the west (parcel No. 23) and a fueling dock access area (parcel 15) on the east. The Muckleshoot property is used for small boat storage and launching. No sources of contamination that would pose a threat to the subject property was observed. A petroleum storage tank and several drums were observed on the parcel to the east (Appendix A, photographs Nos 2 through 4), and could pose a potential contaminant source to the property, albeit minimal. The land immediately north of the property is occupied by the railroad bed belonging to Burlington Northern and the South River Street right-of-way and no contaminant sources were observed in that area. None of the adjoining properties were identified as sites of concern in the Site Assessment Report (Appendix C).

## 3. RECORDS REVIEW

### 3.1 Environmental Records Sources

A Site Assessment Report was developed for the subject property (Vista, Inc. 1998) and is included in Appendix C. Sources utilized in the search included the National Priority List (NPL), list of RCRA permitted treatment, storage, disposal facilities and large and small-quantity hazardous waste generators. EPA Emergency Response Notification System (ERNS - spill

notifications), State of Washington List of affected media sites, state equivalent CERCLIS list, Washington Site Register, Washington Leaking Underground Storage Tanks (LUST) list. The geographic database search meets the ASTM standards for a government records review.

Results indicate the presence of twelve sites of potential concern within a 1/8-mile radius of the property. Of these, four are UST sites, one is a LUST site, four are ERNS sites, One is on the state's contaminated site list (SCL), one is a large-quantity generator and one is a small-quantity generator (SQG). Five of the twelve sites (3 ERNS, 1 UST and 1 SQG) are at the same address: 6701 Fox Avenue S.; the same location as the former Marine Power facility (south side of Slip No. 3). Another two site listings (SCL and ERNS) are for the same address: Franks Used Cars at 6305 E. Marginal Way S. The locations of sites within 1/8 mile of the site are shown in Figure 3.1. A search using the U.S. EPA Region 10 Geographic Information Query System identified an NPDES facility (NPDES ID WA0030899) at Evergreen Marine Leasing - Fox Avenue Facility (47° 32' 33" N; 122° 19' 53" E). The approximate location is shown on Figure 3.1.

The only site within immediate proximity to the subject property is the V. Van Dyke Inc. property at 150 S. River Street; located immediately north (across River Street) from the property. Site files for the WDOT River Street facility (107 River St), the Duwamish Marine Center (16 S. Michigan Street) and Frank's Used Cars (6305 E. Marginal S) were viewed at the Records Department at Ecology's Northwest Regional Office in Bellevue, Washington. There were no files for the V. Van Dyke site, as it is only listed as a UST. Files for the sites at 6701 Fox Avenue S. were not requested since this location is on the opposite side of Slip 3. It is important to note, however, that three of the four ERNS reports within 1/8 mile of the site originate at this location and include releases of oil, diesel fuel and unknown materials to the Duwamish river (the fourth ERNS site is Frank's Used Cars).

V Van Dyke Inc. - 150 S. River Street: A view of this property can be seen in Appendix A, Photo No. 1. Detailed information in the Site Assessment Report (Appendix C - page 14) indicates the site contained four (4) USTs which were removed. Tank contents are listed as unleaded gas, used oil, waste oil and other. No data is available regarding leak monitoring. One tank reportedly contained 1,100 gallons. Since the site is likely to be immediately upgradient of the subject property, there is a possibility that releases of petroleum products to the shallow groundwater table could have migrated under River Street toward the subject property. However, no leak has been reported and the site is not included on the State's LUST listing.

Washington State Department of Transportation - 107 River Street - File contained a UST Notice of Confirmed Release dated 8/18/92. The tank was a "heat fuel" tank - listed as "removed" on 10/21/91. Cleanup status is described as "limited". Comments: "Contamination found during tank removal and accessible PCS [petroleum-contaminated soil] has been removed. Some PCS left in place because of a building. Contamination extends under the building...."

Duwamish Marine Center - 16 S. Michigan Street - Although listed as a large generator in the VISTA Site Assessment Report, Ecology's files included a letter from Ecology dated May 14, 1994 indicating the facility "falls below the fee and planning thresholds for hazardous waste". Most of the materials in the site file concern inspections and complaints dealing with possible improper management or handling of hazardous waste, including sand blast grit, paint wastes, waste oil and wastes which are periodically transferred off ships. Petroleum products have been noted throughout the site by Ecology inspectors.

Franks Used Cars - 6305 E. Marginal Way S.: Ecology's site file included photographs from 1991 showing extensive TPH surface contamination at the site. A "Preliminary Environmental Study" prepared by Environmental Associates Inc. of Bellevue in 1993 indicated the upper 3 ft of soil on south portions of the site are contaminated with heavy fuel oil and certain metals (Cadmium and Lead). One groundwater monitoring well at the site was tested and found to be unaffected by the soil contaminants. Other contaminants of concern listed in the Site Assessment Report (Appendix C) include halogenated organic compounds and solvents.

### 3.2 Physical Setting

The site is located on the north bank of Slip No. 3 extending into the east shore of the Duwamish River. The slip is actually the remnant of an oxbow in the original Duwamish River which was subsequently isolated during the straightening of the river by the Duwamish Waterway Commission - work which began in 1913. The oxbows were eventually filled and platted, except for several of their extreme ends which were converted into slips.

Much of the upland portion of the site appears to be comprised of native riverbank alluvium - chiefly gravel, sand and silt with some clay and peat (Sweet Edwards and Associates, 1985). Fill has likely been used to extend the property southward, and this is confirmed by comparing the shoreline in this vicinity in historical aerial photographs. This fill may also conform to the described as being conveyed to the DeMattea's by the Pacific Construction Company in the legal description of the property. The shoreline area beneath the wharf is comprised of rip-rap to prevent erosion.

A comprehensive description of the Duwamish Valley geology, groundwater, physiography, surface drainage, climate and other features can be found in the Duwamish Ground Water Studies (Sweet Edwards and Associates, 1985 - Draft). Shallow groundwater flow in the site area is likely to be toward the slip, while deeper flow follows the general northward trend (toward Elliott Bay) associated with the valley's alluvial system.

### 3.3 Historical Use

Past use of the property is described in Section 2.6. During the period around the end of World War II, the site was occupied by a shingle mill and several residences. Later, the site was converted into a small commercial/industrial center housing several tenants in one of two buildings erected on the site at 121 and 129 S. River St. A wharf was constructed at the shore sometime between 19xx and 19xx, providing marine access from Slip No. 3 and allowing the use of the site for boat haul-out, storage and refurbishing.

Although not normally included in the scope of a Phase I ESA, the Port of Seattle requested a brief evaluation of archaeological sites in the area and their proximity to the subject site. A review of archaeological sites in the Duwamish River Valley (Figure 3.2) did not reveal any site in the immediate vicinity. Several sites of interest are located upstream and downstream, but are over a mile distant. Additional information on these sites is available (Lewarch et al. 1996).

### 3.4 Offshore Sediment Quality

The condition of sediment in the adjacent Slip No. 3 is pertinent to the unconstrained and beneficial use of the subject property. In the event maintenance dredging is required, disposal of dredge

spoils may be costly due to constraints on disposal imposed by contaminant levels. Adjacent property owners may also be named as potentially responsible parties in the event state or federal agencies determine that sediment cleanup or remediation is necessary.

The quality of sediment in the Duwamish River has been the subject of a number of investigations. Notable among these is the evaluation of potential contaminant sources undertaken as part of the Elliott Bay Action Program (Tetra Tech, 1988). The report, prepared for the US Environmental Protection Agency, identified Slip 3 on the Duwamish River as a "problem station":

"The Fox S. CSO/SD [combined sewer overflow/storm drain] discharges into the Duwamish River approximately 200 ft south [upstream] of Slip 3. Arsenic, zinc, and copper were identified as problem chemicals in sediments from both the Fox S. CSO/SD and Station DR-12 [in Slip 3]. The Fox S. COS/SD station at manhole 3 contained a total of 32 problem chemicals, the largest number in the present study. Based on proximity and close similarity in sediment chemistry between the Fox S. CSO/SD and Station DR-12, the FOS S. CSO/SD may have been a source of sediment contamination observed at Station DR-12. In addition, historical practices at the shipyard along the south shoreline of Slip 3 may have been responsible for metals contamination in Slip 3 sediments (including the use of slag as sandblast grit). No other facilities along the Slip 3 shoreline have been identified as potential contaminant sources."

Chemicals observed to be exceeding the high apparent effects threshold (HAET) value or the 90th percentile concentration were at the aforementioned manhole location were: As, Cu, Pb, Zn, Sb, 4-methylphenol, naphthalene, acenaphthene, fluorene, phenanthrene, anthracene, fluoranthene, pyrene, benzo(a)anthracene, chrysene, benzo(b)fluoranthene, benzo(k)fluoranthene, benzo(a)pyrene, dibenzo(a,h)anthracene, dibenzofuran, 2-methylnaphthalene, 1,1-biphenyl, 1-methylphenanthrene, benzo(a)fluoranthene, ideno(1,2,3-cd)pyrene, HPAH, LPAH, 3-methylphenanthrene, 2-methylphenanthrene, 1,1-dichloroethane, vinyl chloride, trans-1,2-dichloroethene.

Offshore sediment data are available for a sample from the head of Slip 3. This station had the highest score of all Duwamish River stations included in the investigation for chemical contamination and exceeded the 90th percentile for arsenic (449 mg/kg), copper (386 mg/kg), and zinc (969 mg/kg). Lead (307 mg/kg), PCBs, fluoranthene and indeno(1,2,3-cd)pyrene all exceeded LAET (lower apparent affects threshold) concentrations. Marine Power and Equipment shipyard formerly operated along the south edge of Slip 3, and its drydocks and synchrolift were located in Slip 3. During an inspection of Marine Power and Equipment, divers from the U.S. EPA observed sandblast grit in sediment offshore of the shipyard. The heaviest deposits were located beneath the synchrolift.

#### 4. INFORMATION FROM SITE RECONNAISSANCE

Observations made during the site reconnaissance are described below and documented in the photographs included in Appendix A.

#### 4.1 Hazardous Substances in Connection with Identified Uses

None of the identified site uses are associated with use or generation of large quantities of hazardous substances or wastes. Other than materials observed in containers (See Section 4.2 below) no hazardous substances were directly observed that would serve as a source of releases or potential site contamination. There is concern, however, that the long history of storage, fabrication and refurbishing of boats at the site may have resulted in the release of metals to surface soil. This should be evaluated through a limited sampling effort.

#### 4.2 Hazardous Substance Containers and Unidentified Substance Containers

**Interior of Building at 121 S. River St. - Section A (Occupied by Skywalker Industrial):** The company apparently does research on marine propulsion systems. The interior of the CMU building is finished out into separate interior rooms - a machine shop and storage in the south portion, and offices in the north portion. Floors are cast-in-place concrete slab. Heating is by forced air. The storage area included a large boat up on blocks. Items/materials observed in the room included:

- ☐ SafetyKleen parts cleaner station (painted green)
- ☐ approximately one dozen industrial-size fire extinguishers (on floor under bow of the boat)
- ☐ pallet with a 10-gal can of "Rando Oil" (Texaco)
- ☐ One 10-gallon can of kerosene stored on floor.

The center rear of the storage area is occupied by an enclosed machine shop. The room contains a lathe and drill press. Slight oil staining was observed on the concrete floor beneath the drill press, but this is minor and the shop is generally clean. Some small cans of paint were also observed in machine shop area. Storage on top of the machine shop enclosure (Appendix A, photos 33 through 35) included a flammables locker containing a large inventory of small paint cans and miscellaneous solvents (Appendix A, photo No. 36).

The adjoining office areas were observed. Potential ACM acoustical ceiling tile was observed in the office and hall areas (Appendix A, photo No. 39).

**Interior of Building at 121 S. River St. - Section B - Woodworking Shop:** This Building is an add-on to the one described above and is metal-frame with a concrete slab floor. Typical woodworking shop - large planer in center of floor. The room is heated using a butane-fired portable heater and a free-standing wood stove. A large amount of stored wood blocked viewing of much of the area along the south wall and south portion of the east wall. Some 5-gal cans of glue were observed at this location. The occupant indicated a ditch along the interior base of the south wall provided drainage to the building exterior. An electrical panel was observed at the northeast corner of the room. The southwest portion of the room is finished out into a storage room with an upper storage loft. The storage room contained several 10-gal cans of paint (polanes) and small spray paint guns (Appendix A, photo No. 29). A compressor was located at the rear of the room and shows some indication of minor oil leakage. Old fluorescent lights serving the room and stored in the loft may contain PCB ballasts, although no PCB markings were observed.



**Interior of Building at 129 S. River Street:** containers observed inside the building included two 10-gal outboard gas cans (red with flat bottoms) located on floor near east side of office room. No spillage observed. Two drums were observed on a pallet observed in the southeast corner of the building (Appendix A, photo No. 17). One empty drum marked "diesel". The other unmarked drum appears to contain some liquid (unknown - approx. 1/4 full). A small 1-gallon can of unidentified material was present on the floor in the corner at the exterior east side of the bathroom enclosure.

**Wharf Area** - the wharf was clear and well kept. Approximately one-half dozen 5-gal cans of tar material were on the dock - apparently being used to service the barge tied up in the slip (Appendix A, photo No. 40).

#### **4.3 Storage Tanks**

The location of one potential underground storage tank was observed at the southeast corner of the metal-frame building at 129 S. River Street. A possible vent pipe was observed at this location (Appendix A, photograph No. 16).

#### **4.4 Indications of PCBs**

Ballast devices were observed on in-service and out-of-service mercury vapor and fluorescent lamp fixtures located in the buildings at 121 and 129 S. River Street. Inspection of representative ballasts did not reveal any markings or labels indicating the presence or absence of PCBs. Based on the presumed dates of construction of the buildings, there is a potential these devices could contain PCBs.

#### **4.5 Indications of Solid Waste Disposal**

No evidence of on-site solid waste disposal was observed during the site reconnaissance.

#### **4.6 Physical Setting/Cross-Media Contamination**

Observation of adjacent and adjoining properties revealed the proximity of the V. Van Dyke property at the north side of S. River Street (Appendix A, photograph No 1). This site formerly contained four underground storage tanks that were removed. However, there is no documented or observed evidence of any contaminant migration from the V. Van Dyke site. Also, there is some potential for petroleum contamination on the adjoining parcel immediately east of the site (fuel dock access; an above-ground storage tank and several drums were observed on the property. However, access to that site was not available for closer inspection. It is possible some petroleum contamination could migrate onto the subject property.

#### **4.7 Other Conditions of Concern**

An old portable generator was observed in the brush at the east side of the property (Appendix A, Photo No. 6). This unit could still contain fuel, although this could not be confirmed. A old tugboat with rotting hull is present in the open yard area east of the building at 121 S. River Street; there is a potential for hull paint (possible metals) to be dispersed into the surface soil at this location (Appendix A, photo No. 25). A metal sink was observed attached to the exterior portion of the metal-frame building comprising Section A at 121 S. River Street. There are no drain pipes

connected to the sink and buckets are apparently used to catch waste. Possible solvent use at this location (unconfirmed) could result in occasional releases to surrounding ground, although the area appeared to be relatively clean (Appendix A, photos Nos. 23 and 24). Lead ingots were also observed being stored at two locations on pallets at the exterior of the east side of 121 S. River Street (outside Section A - see Appendix A, photos Nos. 26 and 27). However, it is unlikely these ingots are imparting lead contamination to the site as they are unoxidized and relatively uncorroded.

#### 4.8 Site Plan

The site plan is shown in Figure 2.3

### 5. FINDINGS AND CONCLUSIONS

A Phase I Environmental Site Assessment has been performed and reported herein in conformance with the scope and limitations of ASTM practice E1527 of the property at 121 through 165 S. River Street, in Seattle, Washington (see Section 2 for exact location and legal description). This assessment has revealed the following evidence of recognized environmental conditions in connection with the property:

#### Upland Issues:

1. Potential presence of an underground storage tank (UST) at or near the southeast corner of the metal-frame building located at 129 S. River Street. Other possible underground heating oil tanks as may have been associated with residences at 127, 161 and 165 S. River Street (unconfirmed).
2. Past history of boat fabricating and boat storage/refurbishing which could result in the presence of elevated metal concentrations in surface soil (unconfirmed).
3. Possible asbestos-containing acoustical ceiling tile in the office areas of Section A of the building at 121 S. River Street (unconfirmed).
4. Possible PCB-containing ballasts in mercury vapor and fluorescent light fixtures located in both buildings on the property (unconfirmed).
5. The use of the property listed at 127 S. River Street (and probably including 129 S. River St.) for a period of up to 5 years (1978 through 1982) by a company (or companies) known as "Waste Systems International" and "Environmental Emergency Services". Although no above-ground evidence of this use remains, there is potential for soil or subsurface contamination arising from improper storage or accidental spillage that may have resulted from this type of historical use (unconfirmed).
6. Containers (mostly small) of regulated or potentially-regulated materials (polane paints, gasoline, oil, solvents, glues, etc.) at various locations within the two buildings.

Items 1 through 5 should be evaluated further (Phase II evaluation) using established exploratory or testing methods to determine if UST's are present, and to check for potential soil contaminants and other regulated materials listed above that may be present on site. If UST's are determined to be present at the site, then appropriate measures should be taken to report their presence to the

State Department of Ecology, remove them and check for any releases of petroleum products that may be attributed to past or present leakage. The containers of regulated materials are confirmed as being present on site, but will likely be removed by the current tenants. One exception may be the materials observed in the metal-frame building at 129 S. River Street which is presently unoccupied.


#### Adjacent Estuarine Sediment (Slip 3)

1. Presence of contaminants (arsenic, lead, copper, zinc, PCBs and PAH) reported by other investigators in the submerged sediment of Slip No. 3 adjoining the Duwamish River; many of which are in concentrations exceeding state sediment quality standards.

Sediment contamination in the adjacent Slip No. 3 is a concern since ownership of the subject parcels appears to extend into Slip No. 3 to the approximate center-line of the slip. Some assessment of the potential future liability posed by these contaminated sediments should be undertaken, including the potential costs associated with sediment capping or, if necessary to maintain navigability, dredging and disposal of dredged materials.

6. SIGNATURE OF ENVIRONMENTAL PROFESSIONAL

This Phase I Environmental Site Assessment was conducted and prepared by the following Environmental Professional:

  
Warren G. Hansen, PE

January 22, 1998  
(date)

His qualifications are summarized in Appendix D.








FIGURE 2.1 121 THROUGH 165 S. RIVER STREET - REGIONAL MAP







**FIGURE 2.2 PARCEL MAP SHOWING SUBJECT PROPERTY**



Warehouse  
129 S. River Street



House  
127 S. River Street



Front  
Office Bldg  
121 S. River Street



FIGURE 2.3 SITE PLAN SHOWING CURRENT BUILDINGS AND FORMER RESIDENCE  
(courtesy: current owner)




FIGURE 2.4 AERIAL PHOTOGRAPH - 1946 (Walker and Associates)






FIGURE 2.5 SANBORN FIRE INSURANCE MAP - 1949







FIGURE 2.7 AERIAL PHOTOGRAPH - 1974 (Walker and Associates)



YEAR(S)	SOURCE	ADDRESS ON S. RIVER STREET - SEATTLE, WA						
		107	121	127	150	161	167	171
1943-44	Polk	Turley Shingle Co. (107 1/2 - Nelson Louis)	[no listing]	Sklener, John T.	[no listing]	Seth, Wm. H.	Munsell, A. H.	[no listing]
1948-49	Polk	Turley Shingle Co. Turley, J.O. Turley, W.D.	[no listing]	South Seattle Shingle Co.	[no listing]	Seth, Wm. H.	Hatch, W.P. Jr.	Dolce, Thos
1951	Polk	Turley Shingle Co. Turley, J.O. Turley, W.D.	[no listing]	Cascade Shake & Shingle Co.	[no listing]	Seth, Wm. H.	Hatch, W.P. Jr.	Dolce, Thos
1953	Polk	Turley Shingle Co.	[no listing]	[no listing]	[no listing]	Seth, Wm. H.	Hatch, W.P. Jr.	Dolce, Thos
1954	Polk	State Dept. of Highways	[no listing]	[no listing]	[no listing]	Seth, Wm. H.	Vacant	Dolce, Thos
1955	Polk	[no listing]	[no listing]	[no listing]	Mitchell Bros. Truck Line	Seth, Wm. H.	Vacant	Dolce, Thos
1956	Polk	[no listing]	[no listing]	[no listing]	Mitchell Bros. Truck Line	[no listing]	[no listing]	Dolce, Thos
1957	Polk	[no listing]	[no listing]	[no listing]	Mitchell Bros. Truck Line	[no listing]	[no listing]	Dolce, Thos
1958	Polk	[no listing]	Pacific Construction Company - Excavating Contractors	[no listing]	Mitchell Bros. Truck Line			Dolce, Thos
1959	Polk	[no listing]	Pacific Construction Co.	Vacant	Mitchell Bros. Truck Line	[no listing]	[no listing]	Dolce, Thos
1960	Polk	[no listing]	Pacific Construction Co.	[no listing]	Mitchell Bros. Truck Line	[no listing]	[no listing]	Dolce, Thos
1961-62	Polk	[no listing]	Pacific Construction Co.	Stanley Enterprises - mfgs. agents	Mitchell Bros. Truck Line	[no listing]	[no listing]	Dolce, Thos
1963	Polk	[no listing]	Pacific Paving Co. - Rd. Contrs.	Stanley Enterprises	Mitchell Bros. Truck Line	[no listing]	[no listing]	Vacant
1965	Polk	State Dept. of Highways	Pacific Paving Co.	S&E Sales Co. - Electronic Equipmt. Stanley Enterprises	Vacant	[no listing]	[no listing]	Vacant
1966	Polk	State Dept. of Highways	Pacific Paving Co.	Vacant	Duncan Crane & Rigging Inc. - Matls. Handling, Metro Heavy Hauling, Raymond Concrete Pile Yard.	[no listing]	[no listing]	Vacant
1967	Polk	State Dept. of Highways	Pacific Paving Co.	Custom Steel Bldgs Inc. - Bldg. Contrs	Vacant	[no listing]	[no listing]	Vacant
1968	Polk	State Dept. of Highways	Pacific Paving Co.	Custom Steel Bldgs Inc. - Bldg. Contrs	Vacant	[no listing]	[no listing]	Vacant
1970	Polk	State Dept. of Highways	Pacific Paving Co.	Vacant	Vacant	[no listing]	[no listing]	Vacant
1971-72	Polk	State Dept. of Highways	Pacific Paving Co.	Vacant	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]

TABLE 2.1 CITY DIRECTORY SEARCH - 1943-1995

YEAR(S)	SOURCE	ADDRESS ON S. RIVER STREET - SEATTLE, WA						
		107	121	127	150	161	167	171
1973	Polk	State Dept. of Highways	Pacific Paving Co.	Keyes J.R. Co. Inc - Bldg Contrs., Styer, D.C. - Civ. Engr.	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1974	Polk	State Dept. of Highways	Pacific Paving Co.	Hadox Corp Contr equip mfg. & sales	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1975	Polk	State Dept. of Highways	Pacific Paving Co.	Metils Inc. - testing mach.	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1976	Polk	Vacant	Pacific Paving Co.	Metils Inc. - testing mach.	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1977	Polk	Vacant	Pacific Paving Co.	Vacant	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1978	Polk	Vacant	Morton Marine Equipment Pacific Paving, Reagan Marine Services- boat engr/repair, Work Boats Northwest - Bldrs	Critzen Equipment Truck Parts, Waste Systems Intl. - ecology consultants.	Van Champ Horse Van Services Trans Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1979	Polk	Vacant	Morton Marine Equipment Work Boats Northwest - Bldrs	Critzen Equipment Truck Parts, Waste Systems Intl. - ecology consultants.	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1980	Polk	[no return]	Morton Marine Equipment Work Boats Northwest - Bldrs	Environmental Emergency Services	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1983	Polk	Vacant	Morton Marine Equipment Work Boats Northwest - Bldrs	Vacant	Van Dyke Trucking Inc.	[no listing]	[no listing]	Vacant
1985	Polk	State of WA.	Morton Marine Equipment Work Boats Northwest - Bldrs	Vacant	Van Dyke Trucking Inc.	[no listing]	[no listing]	Vacant
1987-88	Polk	State of WA.	Vacant	Vacant	Van Dyke Trucking Inc.	[no listing]	[no listing]	Vacant
1989-90	Polk	State of WA.	Kemp Pacific Fisheries	Vacant	Van Dyke Trucking Inc.	[no listing]	[no listing]	Vacant
1993-94	Cole	[no listing]	[no listing]	[no listing]	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]
1994-95	Cole	[no listing]	[no listing]	[no listing]	Van Dyke Trucking Inc.	[no listing]	[no listing]	[no listing]

TABLE 2.1 CITY DIRECTORY SEARCH - 1943-1995





FIGURE 3.1 SITES WITHIN 1/8 MILE OF PROPERTY





**FIGURE 3.2 ARCHAEOLOGICAL SITES IN THE GREATER SEATTLE VICINITY AND DUWAMISH RIVER VALLEY (Lewarch et al. 1996)**



## REFERENCES

Sweet Edwards and Associates, Inc. 1985. Draft Report - Duwamish Ground Water Studies. Submitted to: Municipality of Metropolitan Seattle. March 31, 1985.

Tetra Tech 1988. Elliott Bay Action Program: Evaluation of Potential Contaminant Sources. Tetra Tech, Inc., Bellevue, Washington. Prepared for U.S. Environmental Protection Agency Region X - Office of Puget Sound, Seattle, Washington. September 1988.

Lewarch et al. 1996. King County Department of Natural Resources Water Pollution Control Division Alki Transfer/CSO Project - Allentown Site (45KI431) and White Lake Site (45KI438 AND 45KI438A) Data Recovery. June 7, 1996.

## APPENDICES

- A. Site Photographs (Current Conditions)
- B. Summary of Historical Aerial Photographs (1936 - 1995)
- C. Site Assessment Report (Vista Information Solutions, Inc.)
- D. Qualifications of Environmental Professional Conducting this Assessment

## APPENDIX A

### SITE PHOTOGRAPHS (CURRENT CONDITION)

Photograph No.	Description.
1.	Property to north - 150 S. River St. (V. Van Dyke Inc.) Location of removed LUST.
2.	Access to parcel east of property (171 S. River St.)
3.	Same as 2 - fence-line.
4.	View into 171 S. River (adjacent property - Note petroleum tank in center of view).
5.	View looking east/southeast at entrance to 171 S. River. SCS Cold storage facility to east. River Street is in foreground.
6.	East side of property, looking south. Note old generator in brush.
7.	Exterior area at east side of property, looking east (SCS Cold Storage in background). Note large float at extreme left. Typical of barnacle-covered floats stored in area east of metal-frame bldg. At 129 S. River.
8.	Open yard area south of bldg at 129 S. River (seen in background).
9.	Same as 7, except taken from further west (looking east). Shows tires and misc. equipment stored in area north of dock.
10.	View to southeast looking in to entrance to property at 121 S. River. Bldg at 129 S. River seen at left. Note boat storage in yard. Grass is in vicinity of former residence (127 S. River).
11.	View to south/southwest from entrance gate - parking area to east of building at 121 S. River St.
12.	Looking west along railroad bed at north side of property. Building at 129 S. River is at left. 1st Avenue Street bridge is in background.
13.	129 S. River Street Building viewed from south. Note green freight container at left (empty).
14.	Same building and container as in 13, looking toward southeast from S. River and Occidental.
15.	Area south of southeast corner of Bldg at 129 S. River. Note large tires stored at this location.
16.	Southeast corner of 129 S. River - note pipe riser at corner of building and concrete pavement under the gray gravel in lower left.
17.	Interior southeast corner of 129 S. River. Two drums on pallet.
18.	Interior south side of 129 S. River. Bags of gypsum and three out-of-service mercury vapor lamps (one is inverted in top of left tire pile).
19.	Interior of south side of 129 S. River. Floor drain is located at base of roll-up door. Dark areas due to water.
20.	Interior of west side of 129 S. River.
21.	Exterior of South side of 121 S. River. Note electrical service (no wet transformers observed) Logs are on west end of dock.
22.	Exterior of east side of 122 S. River - Section B. Trench drain in area flows south to catch basin in foreground. Reddish material on ground is wet sawdust.

23. Same as 22 - note drains in front of roll-up door. Manhole cover marked "Sewer". Note also the metal sink on exterior of bldg.
24. Same sink shown in photo 23. No drains connected to sink. Buckets are used to catch waste. - Possible solvent use at this location could spill to underlying drainage trench and overboard to river. However, area is relatively clean.
25. 121 S. River Bldg (Section B on left, Section A on right). Note old tug in foreground with rotted hull. Possible paint debris in soil at this location.
26. Lead ingots stored on pallet at exterior of east side of 121 S. River (outside Section A).
27. Additional ingots near location shown in photo 26.
28. Covered "test tank" extending from east wall at north end of 121 S. River. Fiberglass tank filled with water for testing propulsion systems. Owner reluctant to allow access to confidential test area. Indicated there are no hydraulics or regulated products associated with the system.
29. Interior of 121 S. River St. Section B - Storage area at floor level at southwest corner. Note paints and glues and spray painting equipment on floor.
30. Interior of Section B - wood working shop. Planer in foreground. Note fluorescent lighting.
31. Interior of Section B - looking south. Note large amount of stored material in rear made inspection of that portion of room impossible. Entrance to floor-level storage area (Photo 29) and storage loft (above) seen at right.
32. Interior of 121 River St. - Section A. View to south (doorway to Section B). Note can of "Rando Oil (Texaco)" on pallet in foreground.
33. View of built-in machine shop in center portion of south side of Section A. (boat seen in photo 32 is at extreme left). Note materials stored on top of machine shop. Note also two mercury-vapor lamps augmenting the fluorescent lighting in this room.
34. Metal ramp providing access to top of shop structure.
35. Top of shop structure looking south from top of stairs (above offices). Note yellow flammables locker in rear-right.
36. Interior of flammables locker shown in Photo 35. Large variety of paints and thinners and other products.
37. Two pails of material located on top of shop in Section A.
38. Interior of south side of Section A (shop and boat are at right). Note partially disassembled engine on sawhorses.
39. Acoustical ceiling tiles typical of office areas in north portion of Section A at 121 S. River Street.
40. Cans of tar material at south (seaward) edge of dock at south side of property. White material on dock is broken barnacle shell residue.
41. Dock at south shore of property, looking east (SCS Cold Storage in background) note crane on dock. Dock surface appeared clean and free of oily sheens. Wood dock is constructed of treated (creosote) wood, but is fairly weathered.
42. Dock at south shore of property looking west. Crane shown in photo 41 is at extreme right.



P  
h  
o  
t  
o  
  
1



P  
h  
o  
t  
o  
  
2





P  
h  
o  
t  
o  
  
3



P  
h  
o  
t  
o  
  
4



P  
h  
o  
t  
o  
  
5



P  
h  
o  
t  
o  
  
6





P  
h  
o  
t  
o  
  
7



P  
h  
o  
t  
o  
  
8





P  
h  
o  
t  
o  
  
9



P  
h  
o  
t  
o  
  
10



P  
h  
o  
t  
o  
  
11



P  
h  
o  
t  
o  
  
12





P  
h  
o  
t  
o  
  
13



P  
h  
o  
t  
o  
  
14



P  
h  
o  
t  
o

15



P  
h  
o  
t  
o

16





P  
h  
o  
t  
o  
  
17



P  
h  
o  
t  
o  
  
18



P  
h  
o  
t  
o  
  
19



P  
h  
o  
t  
o  
  
20





P  
h  
o  
t  
o  
  
21



P  
h  
o  
t  
o  
  
22





P  
h  
o  
t  
o  
  
23



P  
h  
o  
t  
o  
  
24



P  
h  
o  
t  
o  
  
25



P  
h  
o  
t  
o  
  
26






P  
h  
o  
t  
o

27




P  
h  
o  
t  
o

28



P  
h  
o  
t  
o

29



P  
h  
o  
t  
o

30





P  
h  
o  
t  
o  
  
31



P  
h  
o  
t  
o  
  
32



P  
h  
o  
t  
o

33



P  
h  
o  
t  
o

34





# Photo

35



Photo

36





P  
h  
o  
t  
o  
  
37



P  
h  
o  
t  
o  
  
38



P  
h  
o  
t  
o  
  
39



P  
h  
o  
t  
o  
  
40





P  
h  
o  
t  
o  
  
41



P  
h  
o  
t  
o  
  
42

## APPENDIX B

### SUMMARY OF HISTORICAL AERIAL PHOTOGRAPHS (1936 - to - 1995)

Photographs viewed at Walker and Associates, Inc., 12652 Interurban Avenue South, Seattle, WA  
January 07, 1998.

Date: 1936    Scale: 1 in = 800 ft.

Structures appearing to be a lumber mill are on the property west of the site. Area west of Occidental Avenue is clear (undeveloped). Original Duwamish oxbow has been recently filled and is apparent. Residence observed in later photos is not present.

Date: 1946    Scale: 1 in = 1,000 ft.

Enlarged portion of this photograph is attached. Site is clear except for a square structure (shingle mill) in the center of the property (current parking area), several trees (/) and a smaller shed or residence located north of the aforementioned square structure (see copy: 1946 - photo by Walker and Associates). Structure appearing to be a sawmill is located on property to the west (between site and bridge). Small pier-like structure extends out into the water from the south shore.

Date: 1956    Scale 1 in. = 1,000 ft

Photograph is very obscure. A graded, smoothed-off area is observed in the future location of the building at 121 S. River Street - Bldg Section A. There is a residence building located in the north, central portion of the site, immediately west of the future site of the east building (129 S. River Street). This residence corresponds with the House at 127 S. River Street shown on the map provided by Mr. Rasmussen. The same residence can be vaguely observed in the 1974 map provided by Walker and Associates (attached).

Date: 1960.    Scale 1 in = 1,000 ft

Photograph somewhat obscure. Section A of the building at 121 S. River is now present at the west side of the site. Miscellaneous buildings are still present to the east. Row of unidentified structures (boats ?) are observed along the south side of the property (along the shoreline).

Date: 1969.    Scale 1 in = 2,000 ft

Residence still present. Section B of the building at 121 S. River appears. Large cold storage building now present on north shore of slip 3 - east of the site.

Date: 1974.    Scale 1 in = 2,000 ft

Enlarged copy of photograph is attached (1974 - photo by Walker and Associates). All buildings present (121 River, Sections A and B; 127 River (residence) and 129 river (metal-frame building). Extensive log storage observed in east and south portions of property.

Date 1980: Scale 1 in = 1,000 ft

Same as 1985 (see below). Small dark (oily or wet) areas on soil in center of parking area and near west building (121 River).

Date 1985. Scale 1 in = 1,000 ft.

Additional (temporary) building or covered pile observed in yard at south side of east metal frame building (129 River St.) - NOTE: this is the same building shown in the 1986 Port of Seattle Map (Figure 2.8). Large amount of miscellaneous material stored in yard (ship/barge refitting?). Soil appears disturbed from extensive site activity and on-site storage.

Date: 1990. Scale 1 in = 1,000 ft

Color Photo. Logs stored on property. Two shed-like structures observed immediately south of the southwest corner of east building (129 River St.). Surface soils look clean - no oily or dark areas. Bldg observed extending from west side of east building. This could still be the residence. Dock now present along south shore of property.

Date: 1995. Scale 1 in = 2,000 ft.

Site layout essentially same as observed during site visit on January 1998. Large fishing floats are seen in the area east and southeast of the east building (129 S. River St). Green freight container is present at the west side of same building.

**APPENDIX C**


**SITE ASSESSMENT REPORT  
VISTA INFORMATION SOLUTIONS, INC.  
SAN DIEGO, CALIFORNIA**

**[JANUARY 2, 1998]**

# SITE ASSESSMENT REPORT


PROPERTY INFORMATION	CLIENT INFORMATION
Project Name/Ref #: SILVER BAY LOGG SILVER BAY LOGGING 121-171 S RIVER ST SEATTLE, WA 98108 Cross Street: LAT/LONG 47 32 34/ 122 19 57 Latitude/Longitude: ( 47.543448, 122.331363 )	WARREN HANSEN ONSITE ENTERPRISES INC-REDMOND 6605 146 AVE NE REDMOND, WA 98052

Site Distribution Summary			within 1/8 mile	1/8 to 1/4 mile	1/4 to 1/2 mile	1/2 to 1 mile
<b>Agency / Database - Type of Records</b>						
<b>A) Databases searched to 1 mile:</b>						
US EPA	NPL	National Priority List	0	0	0	0
US EPA	CORRACTS (TSD)	RCRA Corrective Actions and associated TSD	0	1	0	2
STATE	SPL	State equivalent priority list	0	1	2	7
STATE	SCL	State equivalent CERCLIS list	1	0	5	17
<b>B) Databases searched to 1/2 mile:</b>						
US EPA	CERCLIS / NFRAP	Sites currently or formerly under review by US EPA	0	1	4	-
US EPA	TSD	RCRA permitted treatment, storage, disposal facilities	0	0	0	-
STATE	LUST	Leaking Underground Storage Tanks	1	5	20	-
STATE	SWLF	Permitted as solid waste landfills, incinerators, or transfer stations	0	0	2	-
STATE	TOXICS	Washington Site Register	1	2	8	-
<b>C) Databases searched to 1/4 mile:</b>						
STATE	UST	Registered underground storage tanks	4	5	-	-
<b>D) Databases searched to 1/8 mile:</b>						
US EPA	ERNS	Emergency Response Notification System of spills	4	-	-	-
US EPA	LG GEN	RCRA registered large generators of hazardous waste	1	-	-	-
US EPA	SM GEN	RCRA registered small generators of hazardous waste	1	-	-	-










# SITE ASSESSMENT REPORT

## Map of Sites within One Mile




Subject Site	Category:	A	B	C	D
	Databases Searched to:	1 mi.	1/2 mi.	1/4 mi.	1/8 mi.
★	Single Sites	◆	■	▲	○
	Multiple Sites	◆◆	■■	▲▲	○○
	Highways and Major Roads	NPL, SPL, CORRACTS (TSD), SCL	CERCLIS, NFRAP, TSD, LUST, SWLF	UST	ERNS, GENERATORS
	Roads				
	Railroads				
	Rivers or Water Bodies				
	Utilities				

For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403

Report ID: 153929001


Date of Report: January 2, 1998

Page #3



# SITE ASSESSMENT REPORT

## Map of Sites within Quarter Mile




Subject Site	Category:			
	Databases Searched to:			
★	Single Sites	A 1 mi.	B 1/2 mi.	C 1/4 mi.
	Multiple Sites	D 1/8 mi.		
	Highways and Major Roads			
	Roads			
	Railroads			
	Rivers or Water Bodies			
	Utilities			

For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403  
Report ID: 153929001


Date of Report: January 2, 1998

Page #4



# SITE ASSESSMENT REPORT

## Street Map



# SITE ASSESSMENT REPORT

## SITE INVENTORY

MAP ID	PROPERTY AND THE ADJACENT AREA (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	A				B				C	D			
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
1A	WDOT RIVER STREET 107 RIVER ST SEATTLE, WA	3629364 0.00 MI NA							X						
1A	V. VAN DYKE INC. 150 S. RIVER ST. SEATTLE, WA 98108	1849126 0.00 MI NA										X			
1B	WF CARMODY 220 S RIVER ST SEATTLE, WA 98108	1849128 0.00 MI NA										X			
2	SEATTLE TRUCK REPAIR INC 6401 OCCIDENTAL AVE SOUTH SEATTLE, WA 98108	1847480 0.02 MI N										X			
3	DUWAMISH MARINE CTR INC 16 S MICHIGAN ST SEATTLE, WA 98108	3271854 0.03 MI W												X	
4	FRANKS USED CARS 6305 E MARGINAL WAY S SEATTLE, WA 98108	1855682 0.08 MI NE				X					X				
4	FRANKS USED CARS 6305 E MARGINAL S SEATTLE, WA	200091389 0.08 MI NE											X		
5	HIGHLAND LIGHT CORP 6701 FOX AVE SOUTH SEATTLE, WA 98108	200385487 0.09 MI E											X		
5	FV HIGHLAND LIGHT 6701 FOX AVE SEATTLE, WA 98108	200385486 0.09 MI E											X		
5	NORTHLAND SVCS INC 6701 FOX AVE S SEATTLE, WA 981083417	4072136 0.10 MI E													X
5	KEMP PACIFIC SEAFOODS ** 6701 FOX AV S SEATTLE, WA	200156878 0.10 MI E											X		
5	NORTHLAND SERVICES INC 6701 FOX AVE. SO. SEATTLE, WA 98108	3885457 0.10 MI E										X			

X = search criteria; . = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #6



MAP ID	SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)	VISTA ID DISTANCE DIRECTION	A				B				C	D		
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN
6	RAY BURGESS CO 6361 FIRST AVE S SEATTLE, WA 98108	3269759 0.18 MI NW										X		
7	EVERCLEAN INC DBA GAS N WASH 551 S MICHIGAN ST SEATTLE, WA 98108	5377873 0.22 MI NE							X			X		•
7	GAS N WASH 551 S MICHIGAN ST SEATTLE, WA 98108	1849624 0.22 MI NE							X		X			
8A	SEAFREEZE LIMITED PARTNERSHIP 210 SW MICHIGAN PO BOX 24978 SEATTLE, WA 98124	1845959 0.22 MI SW										X		
8B	ALASKA MARINE LINES 2ND AVE SW 7100 2ND AVENUE SW SEATTLE, WA 98106	9996 0.24 MI SW							X			X		
9	GREAT WESTERN CHEMICAL CO 6900 FOX AVE SEATTLE, WA 98105	179431 0.24 MI SE		X			X		X					•
9	GREAT WESTERN CHEMICAL 6900 FOX AV S SEATTLE, WA 98108	6959837 0.24 MI SE			X									
9	GREAT WESTERN CHEMICAL CO 6900 FOX AVE. SOUTH SEATTLE, WA 98108	1844645 0.24 MI SE							X		X	X		

MAP ID	SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)	VISTA ID DISTANCE DIRECTION	A				B				C	D			
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
10	CONSOLIDATED FREIGHTWAYS 6050 E MARGINAL WAY S SEATTLE, WA 98108	97635 0.27 MI N							X		X	•			•
11	EMERALD TOOL INC 6332 6TH S SEATTLE, WA 98108	3270552 0.29 MI E					X								•
11	AND ALL ELECTROCHROME INC 6332 6TH S SEATTLE, WA 98108	84 0.30 MI E			X										
11	TEXACO STATION # 63 232 1455 600 S MICHIGAN SEATTLE, WA 98108	5731939 0.32 MI NE							X		X	•			•

X = search criteria; • = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.


Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #7

MAP ID	SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)	VISTA ID DISTANCE DIRECTION	A			B				C	D				
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
11	PENINSULA TRUCK LINES 6314 7TH S SEATTLE, WA 98108	324077 0.35 MI E							X						.
11	PTL PARTNERSHIP 6314 7TH S SEATTLE, WA 98108	1841830 0.35 MI E							X		.				
12	LONE STAR (CONCRETE) NW 5975 E MARGINAL WAY S SEATTLE, WA 98134	4267290 0.35 MI N							X		.				
12	CHEVRON USA INC SS 90636 590 E MARGINAL WAY SEATTLE, WA 98134	81774 0.37 MI N							X		X	.			.
12	JAMES HARDIE GYPSUM 5931 E. MARGINAL WAY SO. SEATTLE, WA 98134	187277 0.37 MI N				X			X		X	.			.
12	LONGVIEW FIBRE COMPANY 5901 EAST MARGINAL WAY SOUTH SEATTLE, WA 98134	249440 0.39 MI N			X				X		X	.		.	
13	JONES WASHINGTON STEVEDORING 7245 W.MARGINAL WAY S.W. SEATTLE, WA 98106	1846655 0.38 MI SW							X			.			
14	DNR CORSON - 6655; 6715; 6737 CORSON 6737 CORSON AVENUE SOUTH SEATTLE, WA 98108	1854465 0.39 MI E							X						
14	ARROW TRANSPORTATION 6737 CORSON S SEATTLE, WA 98108	209546 0.39 MI E				X	X		X			.			
15	SUNSET DISPOSAL 7201 W MARGINAL WAY SW SEATTLE, WA 98146	5749840 0.39 MI SW							X			.			
15	WASTE MANAGEMENT SEATTLE 7201 W MARGINAL WAY SW SEATTLE, WA 98146	40433 0.39 MI SW				X			X		X				.
15	BAYSIDE DISPOSAL CO 7201 W MARGINAL WAY S SEATTLE, WA 98106	3509044 0.39 MI SW				X	X								
15	WASTE MANAGEMENT OF SEATTLE , WA	4287932 0.39 MI SW								X					
16	BEN'S TRUCK PARTS 6655 CORSON AVENUE SOUTH SEATTLE, WA 98108	6782638 0.40 MI E							X						
17	SAHLBERG EQUIPMENT 5950 4TH AV S SEATTLE, WA 98108	4917627 0.41 MI NE				X					X				



X = search criteria; . = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #8

MAP ID	SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)	VISTA ID DISTANCE DIRECTION	A				B				C	D			
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
18	MOBILE CRANE AKA WESTERN BRIDGE CO 5900 SECOND AVE SO SEATTLE, WA 98108	5377772 0.42 MI N							X						
18	WESTERN BRIDGE CO 5900 SECOND AVE SO SEATTLE, WA 98108	1840743 0.45 MI N							X			•			
19	EASTMONT TRANSFER STATION 7155 W MARGINAL WY SW SEATTLE, WA 98106	5165444 0.43 MI W								X					
20	SEATTLE, CY OF, 1ST AV BRG LDFL E MARGINAL WY S FIDALGO ST SEATTLE, WA 98108	373103 0.44 MI N					X								
20	INCON PACKAGING 5801 EAST MARGINAL WAY SOUTH SEATTLE, WA 98134	6607455 0.46 MI N							X						
21	WDOT CORSON 6431 CORSON AVE S SEATTLE, WA 98108	1856056 0.46 MI E							X						
21	DISTRICT HEADQUARTERS SITE 6431 CORSON AVE S SEATTLE, WA 98108	1843513 0.46 MI E							X			•			
22	FERGUSON CONSTRUCTION 7433 5TH AVE S SEATTLE, WA	1853579 0.47 MI SE							X		X				

MAP ID	SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)	VISTA ID DISTANCE DIRECTION	A				B				C	D			
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
23	BOEING NORTH FIELD ELLIS AV E MARGINAL WY SEATTLE, WA 98108	6783364 0.57 MI E			X										
23	BOEING NORTH FIELD JP4 TANKS ELLIS AV E MARGINAL WY SEATTLE, WA 98108	6783140 0.58 MI E				X									
23	STERNOFF METALS 7201 E MARGINAL WAY S SEATTLE, WA 98108	399610 0.59 MI E			X		•								
24	FIRST AV BRIDGE LANDFILL 7700 BLOCK OF 2ND AV SW SEATTLE, WA 98106	1854090 0.62 MI S				X									

X = search criteria; • = tag-along (beyond search criteria).


For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #9



MAP ID	SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)	VISTA ID DISTANCE DIRECTION	A			B				C	D				
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
24	EASTERN SUPPLY CO 7745 1ST AV S SEATTLE, WA 98108	2882786 0.62 MI S			X										
25	WEST COAST EQUIPMENT INC 7777 DETROIT AV SW SEATTLE, WA 98106	1854572 0.64 MI SW				X									
26	MASTER BUILDERS 64 S LUCILE ST SEATTLE, WA 98134	1855279 0.66 MI N				X									
27	MST CHEMICALS INC 6020 W MARGINAL SW SEATTLE, WA 98106	1855689 0.67 MI NW				X									
27	REICHOLD CHEMICAL LONE STAR 5900 W MARGINAL WAY SW SEATTLE, WA 98106	2884087 0.71 MI NW			X										
28	SEATTLE COMMERCIAL FINISHING 5700 CORSON AV S SEATTLE, WA 98108	2820 0.72 MI NE				X									
29	SEATTLE S TRANSFER STA 8100 2ND AV S SEATTLE, WA 98108	6959767 0.73 MI S				X									
30	INTERSTATE COATINGS INC 754 S CHICAGO ST SEATTLE, WA 981084321	537533 0.77 MI SE				X						•		•	
31	BURL ENV INC DBA PHILIP ENV INC LUCILE 734 S LUCILE ST SEATTLE, WA 98108	6607395 0.79 MI NE		X										•	
31	CHEMICAL PROCESSORS INC/LUCILE 734 S LUCILE ST SEATTLE, WA 98108	79440 0.79 MI NE				X									
32	DUWAMISH SHIPYARD INC 5658 W MARGINAL WAY SW SEATTLE, WA 981061596	130505 0.80 MI NW				X						•		•	
32	WRIGHT SCHUCHART HARBOR CO SEATTLE 5500 W MARGINAL WAY SW SEATTLE, WA 98106	475943 0.87 MI NW				X									
33	KING AUTO TRUCK WRECKING 543 S MONROE SEATTLE, WA 98108	1855587 0.81 MI SE				X									
34	PIONEER ENAMEL MFG CO INC 5531 AIRPORT WAY S SEATTLE, WA 98108	331364 0.81 MI NE			X		•								
35	GENERAL ELECTRIC CO SEATTLE DAWSON 220 S DAWSON ST SEATTLE, WA 98108	167631 0.84 MI N	X	X						•				•	

X = search criteria; • = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #10

MAP ID	SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)	VISTA ID DISTANCE DIRECTION	A				B				C	D			
			NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
36	NORTHWEST ENVIROSERVICE INC 8105 1ST AVE S SEATTLE, WA 98108	4071706 0.86 MI S				X									•
37	PRESERVATIVE PAINT CO 5410 AIRPORT WAY SOUTH SEATTLE, WA 98108	338638 0.87 MI NE				X	•		•			•			•
38	CRAIG TAYLOR EQUIPMENT 5030 1ST AVE S SEATTLE, WA	1852533 0.89 MI N				X			•						
39	MARINE VACUUM SVC INC 1516 S GRAHAM ST SEATTLE, WA 98108	260641 0.94 MI E			X									•	
39	NORTH COAST CHEMICAL 6300 17TH AVE S SEATTLE, WA	299754 0.98 MI E				X	•		•		•				
40	MANITOWOC WESTERN 8250 5TH AVE S SEATTLE, WA 981084533	6499806 0.97 MI S				X								•	

X = search criteria; • = tag-along (beyond search criteria).


For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998


Version 2.5

Page #11





UNMAPPED SITES	VISTA ID	A				B				C	D			
		NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN	SM GEN
LIDLAW 7739 1ST AV S SEATTLE, WA 98108	6959750			X										
METRO POWER DISTRIBUTION HQ 2255 44TH AVE. S. SEATTLE, WA 98134	6808295									X				
80TH S. HUDSON ST. 80TH S. HUDSON ST. SEATTLE, WA 98134	6808378									X				
NORTHWEST COOPERAGE CO., INC. 7152 1ST AVE. SOUTH SEATTLE, WA 98108	6808193									X				
TERMINAL 30 PORT OF SEATTLE SEATTLE, WA 98134	6807976									X				
SW HARBOR PROJ WYCKOFF W MARGINAL WY SW FLORIDA ST SW SEATTLE, WA 98134	6783416				X									
TERMINAL 18 PORT OF SEATTLE SEATTLE, WA 98134	6807975									X				
TERMINAL 106 PORT OF SEATTLE SEATTLE, WA 98134	6807974									X				
HORTON ST. MAINTENANCE SHOP PORT OF SEATTLE SEATTLE, WA 98134	6807973									X				
PUGET PARK 16TH AV SW SEATTLE, WA 98106	6959760				X									
KING CO - SOUTHPARK LDFL S PARK, W OF 5TH AV S ROSE SEATTLE, WA 98106	229386					X								
MELTON'S HEATING TANK 17767 15TH AVE. NW SEATTLE, WA 98108	6808134									X				
SOUTHPARK LANDFILL S PARK SEATTLE, WA 98108	6959924				X									
BOEING - NORTH BOEING FIELD TRAINING FA KING COUNTY AIRPORT SEATTLE, WA 98108	5189276									X				
BOW LAKE TRANSFER STATION 18800 ORILLIA RD S TUKWILA, WA	5165450							X						



X = search criteria; • = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.


Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #12

UNMAPPED SITES	VISTA ID	A				B				C	D		
		NPL	CORRACTS(TSD)	SPL	SCL	CERCLIS/NFRAP	TSD	LUST	SWLF	TOXICS	UST	ERNS	LG GEN
SEATAC AIRPORT - PAN AM HANGER PORT OF SEATTLE SEATTLE, WA 98108	6807969								X				
NORTHWEST ENVIROSERVICE 2W 1ST AV SW MARGINAL SEATTLE, WA 98108	6959874				X								
NORTHWEST ENVIRO SERVICE 1ST AVE. S. SEATTLE, WA 98108	5411762								X				
BOEING FIELD - NORTH MAIN FUEL FARM SE OF BLDG 3-465 SEATTLE, WA 98108	5412382								X				
SEATAC CRAWFORD AVIATION SEATAC INTERNATIONAL AIRPORT SEATAC, WA 98168	4686193						X		X				
AMERICAN AVIONICS 7031 PERIMTER ROAD S. SEATTLE, WA 98108	7044967								X				
CITY OF SEATTLE/UNION PACIFIC RR RIGHT- 7500 BLOCK OF E. MARGINAL WAY SEATTLE, WA 98108	6808441								X				
CHEVRON STATION # 9-5257 8808 271ST ST NW SEATTLE, WA 98111	5027907						X		X	X			
MOBIL STATION - HAYES BROTHERS 101 S. 111TH ST. SEATTLE, WA 98138	6808057								X				



X = search criteria; • = tag-along (beyond search criteria).

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #13

# SITE ASSESSMENT REPORT

## DETAILS

### PROPERTY AND THE ADJACENT AREA (within 1/8 mile)

VISTA Address*:	WDOT RIVER STREET 107 RIVER ST SEATTLE, WA	VISTA ID#:	3629364
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE LUST - State Leaking Underground Storage Tank / SRC# 2761		Agency ID:	3806

Map ID

**1A**

Agency Address:	SAME AS ABOVE
Tank Status:	NOT AVAILABLE
Discovery Date:	AUGUST 18, 1992
Media Affected:	SOIL/LAND/SAND
Substance:	NOT AVAILABLE
Leak Cause:	UNAVAILABLE
Leak Source:	NOT AVAILABLE
Remedial Action:	NOT AVAILABLE
Remedial Status 1:	CLEANUP IN PROGRESS/REQUIRED
Remedial Status 2:	NOT AVAILABLE
Fields Not Reported:	Quantity (Units)

STATE LUST - State Leaking Underground Storage Tank / SRC# 4113	Agency ID:	200163
---	------------	--------

Agency Address:	SAME AS ABOVE
Tank Status:	NOT AVAILABLE
Discovery Date:	AUGUST 18, 1992
Media Affected:	SOIL/LAND/SAND
Substance:	NOT AVAILABLE
Leak Cause:	UNAVAILABLE
Leak Source:	NOT AVAILABLE
Remedial Action:	NOT AVAILABLE
Remedial Status 1:	CLEANUP IN PROGRESS/REQUIRED
Remedial Status 2:	NOT AVAILABLE
Fields Not Reported:	Quantity (Units)

VISTA Address*:	V. VAN DYKE INC. 150 S. RIVER ST. SEATTLE, WA 98108	VISTA ID#:	1849126
		Distance/Direction:	0.00 MI / NA
		Plotted as:	Point
STATE UST - State Underground Storage Tank / SRC# 4114		Agency ID:	12577

Map ID

**1A**

Agency Address:	SAME AS ABOVE		
Underground Tanks:	4		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	4		
Tank ID:	1U	Tank Status:	REMOVED
Tank Contents:	OTHER	Leak Monitoring:	NOT AVAILABLE
Tank Age:	33	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)	Tank Material:	NOT AVAILABLE

\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #14

**PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.**


<b>Tank ID:</b>	2U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	UNLEADED GAS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	NOT AVAILABLE
<b>Tank ID:</b>	3U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	NOT AVAILABLE
<b>Tank ID:</b>	4U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	USED OIL, WASTE OIL	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	NOT AVAILABLE
<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>		<b>Agency ID:</b>	1364
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Underground Tanks:</b>		2	
<b>Aboveground Tanks:</b>		NOT REPORTED	
<b>Tanks Removed:</b>		2	
<b>Tank ID:</b>	1U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	2U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	UNLEADED GAS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	1100 (GALLONS)	<b>Tank Material:</b>	STEEL

<b>VISTA Address*:</b>	<b>WF CARMODY 220 S RIVER ST SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1849128
		<b>Distance/Direction:</b>	0.00 MI / NA
		<b>Plotted as:</b>	Point
<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>		<b>Agency ID:</b>	97212

Map ID

**1B**

<b>Agency Address:</b>		SAME AS ABOVE	
<b>Underground Tanks:</b>		3	
<b>Aboveground Tanks:</b>		NOT REPORTED	
<b>Tanks Removed:</b>		NOT REPORTED	
<b>Tank ID:</b>	1U	<b>Tank Status:</b>	CLOSED IN PLACE
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	2U	<b>Tank Status:</b>	CLOSED IN PLACE
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	3U	<b>Tank Status:</b>	CLOSED IN PLACE
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #15



**PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.**

<b>VISTA Address*:</b>	<b>SEATTLE TRUCK REPAIR INC</b> <b>6401 OCCIDENTAL AVE SOUTH</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1847480
		<b>Distance/Direction:</b>	0.02 MI / N
		<b>Plotted as:</b>	Point
<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>		<b>Agency ID:</b>	1984
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Underground Tanks:</b>	2		
<b>Aboveground Tanks:</b>	NOT REPORTED		
<b>Tanks Removed:</b>	2		
<b>Tank ID:</b>	1U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	UNLEADED GAS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	1U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL

Map ID

**2**

<b>VISTA Address*:</b>	<b>DUWAMISH MARINE CTR INC</b> <b>16 S MICHIGAN ST</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	3271854
		<b>Distance/Direction:</b>	0.03 MI / W
		<b>Plotted as:</b>	Point
<b>RCRA-LgGen - RCRA-Large Generator / SRC# 3946</b>		<b>EPA ID:</b>	WAD988504999
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Generator Class:</b>	Generates at least 1000 kg./month of non-acutely hazardous waste ( or 1 kg./month of acutely hazardous waste).		


Map ID

**3**

<b>VISTA Address*:</b>	<b>FRANKS USED CARS</b> <b>6305 E MARGINAL WAY S</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1855682
		<b>Distance/Direction:</b>	0.08 MI / NE
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2337 WARM
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	INDEPENDENT REMEDIAL ACTION, INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV		
<b>Pollutant 1:</b>	HALOGENATED ORGANIC COMPOUNDS		
<b>Pollutant 2:</b>	PETROLEUM		
<b>Pollutant 3:</b>	SOLVENTS		
<b>WA Toxics - Washington Toxics / SRC# 4061</b>		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	FRANK'S USED CARS 6305 E. MARGINAL WAY S. SEATTLE, WA 98108		
<b>Region:</b>	NORTHWEST		
<b>State Detail Description:</b>	NO		
<b>Contact:</b>	NOT REPORTED		
<b>Description:</b>	WASTE: METALS		
<b>Description:</b>	WASTE: PETROLEUM PRODUCT		
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT: 1/25/93 0:00:00		
<b>Description:</b>	MEDIA: SOIL		
<b>Description:</b>	REPORT TYPE: INTERIM		
<b>Description:</b>	ISSUE OF SITE REGISTER: 92-42		

Map ID

**4**



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #16

**PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.**

VISTA Address*:	<b>FRANKS USED CARS</b> <b>6305 E MARGINAL S</b> <b>SEATTLE, WA</b>	VISTA ID#:	200091389
		Distance/Direction:	0.08 MI / NE
		Plotted as:	Point
<b>ERNS - Emergency Response Notification System / SRC# 4144</b>		Agency ID:	90130
Agency Address:		SAME AS ABOVE	
Spill Date Time:		APRIL 3, 1990 00:00:00 PM	
Case Number:		90130	
Spill Location:		6305 E MARGINAL S	
Source Agency:		E	
Discharger Org:		FRANKS USED CARS	
Waterway Affected:		NONE	
Fields Not Reported:		Discharger Name, Discharger Phone, Material Spilled	
Air Release:	Land Release:	Water Release:	Ground Release: Facility Release: Other Release:
NO	YES	NO	NO NO NO

Map ID

**4**

VISTA Address*:	<b>HIGHLAND LIGHT CORP</b> <b>6701 FOX AVE SOUTH</b> <b>SEATTLE, WA 98108</b>	VISTA ID#:	200385487
		Distance/Direction:	0.09 MI / E
		Plotted as:	Point
<b>ERNS - Emergency Response Notification System / SRC# 4144</b>		Agency ID:	319141
Agency Address:		HIGHLAND LIGHT CORP 6701 FOX AVE SOUTH SEATTLE, WA 98107	
Spill Date Time:		JANUARY 5, 1996 02:15:00 PM	
Case Number:		319141	
Spill Location:		6701 FOX AVE SOUTH	
Discharger Org:		HIGHLAND LIGHT CORP	
Material Spilled:		OIL: DIESEL, 3.00 (GAL)	
Waterway Affected:		DUWAMISH WATERWAY	
Fields Not Reported:		Source Agency, Discharger Name, Discharger Phone	
Air Release:	Land Release:	Water Release:	Ground Release: Facility Release: Other Release:
NO	NO	YES	NO NO NO

Map ID

**5**

VISTA Address*:	<b>F/V HIGHLAND LIGHT</b> <b>6701 FOX AVE</b> <b>SEATTLE, WA 98108</b>	VISTA ID#:	200385486
		Distance/Direction:	0.09 MI / E
		Plotted as:	Point
<b>ERNS - Emergency Response Notification System / SRC# 4144</b>		Agency ID:	319140
Agency Address:		F/V HIGHLAND LIGHT 6701 FOX AVE SEATTLE, WA	
Spill Date Time:		JANUARY 5, 1996 02:30:00 PM	
Case Number:		319140	
Spill Location:		6701 FOX AVE	
Discharger Org:		F/V HIGHLAND LIGHT	
Material Spilled:		UNKNOWN MATERIAL, 0.00 (UNK)	
Waterway Affected:		DUWAMISH RIVER	
Fields Not Reported:		Source Agency, Discharger Name, Discharger Phone	
Air Release:	Land Release:	Water Release:	Ground Release: Facility Release: Other Release:
NO	NO	YES	NO NO NO

Map ID

**5**

\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #17

**PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.**

VISTA Address*:	<b>NORTHLAND SVCS INC 6701 FOX AVE S SEATTLE, WA 981083417</b>	VISTA ID#:	4072136
		Distance/Direction:	0.10 MI / E
		Plotted as:	Point
<b>RCRA-SmGen - RCRA-Small Generator / SRC# 3946</b>		EPA ID:	WAD980977128
Agency Address:	SAME AS ABOVE		
Generator Class:	Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous waste		

Map ID

**5**

VISTA Address*:	<b>KEMP PACIFIC SEAFOODS ** 6701 FOX AV S SEATTLE, WA</b>	VISTA ID#:	200156878
		Distance/Direction:	0.10 MI / E
		Plotted as:	Point
<b>ERNS - Emergency Response Notification System / SRC# 4144</b>		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Spill Date Time:	MAY 12, 1988 06:30:00 AM		
Spill Location:	6701 FOX AV S		
Discharger Org:	KEMP PACIFIC SEAFOODS **		
Material Spilled:	DIESEL FUEL, 20.00 (GAL)		
Waterway Affected:	DUWAMISH RIVER		
Fields Not Reported:	Case Number, Source Agency, Discharger Name, Discharger Phone		
Air Release:	Land Release:	Water Release:	Ground Release: Facility Release: Other Release:
NO	NO	YES	NO NO NO


Map ID

**5**

VISTA Address*:	<b>NORTHLAND SERVICES INC 6701 FOX AVE. SO. SEATTLE, WA 98108</b>	VISTA ID#:	3885457
		Distance/Direction:	0.10 MI / E
		Plotted as:	Point
<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>		Agency ID:	11256
Agency Address:	SAME AS ABOVE		
Underground Tanks:	3		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	2		
Tank ID:	1U	Tank Status:	REMOVED
Tank Contents:	LEADED GAS	Leak Monitoring:	NOT AVAILABLE
Tank Age:	33	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	1100 (GALLONS)	Tank Material:	STEEL
Tank ID:	2U	Tank Status:	EXEMPT
Tank Contents:	OTHER	Leak Monitoring:	NOT AVAILABLE
Tank Age:	33	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	1100 (GALLONS)	Tank Material:	STEEL
Tank ID:	3U	Tank Status:	REMOVED
Tank Contents:	OTHER	Leak Monitoring:	NOT AVAILABLE
Tank Age:	33	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)	Tank Material:	STEEL

Map ID

**5**



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #18

**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)**

VISTA Address*:	<b>RAY BURGESS CO 6361 FIRST AVE S SEATTLE, WA 98108</b>	VISTA ID#:	3269759
		Distance/Direction:	0.18 MI / NW
		Plotted as:	Point

Map ID  
**6**

<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>	Agency ID:	101434
---	------------	--------

Agency Address:		SAME AS ABOVE	
Underground Tanks:		1	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	
Tank ID:	1U	Tank Status:	CLOSURE PENDING
Tank Contents:	LEADED GAS	Leak Monitoring:	NOT AVAILABLE
Tank Age:	33	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)	Tank Material:	NOT AVAILABLE

VISTA Address*:	<b>EVERCLEAN INC DBA GAS N WASH 551 S MICHIGAN ST SEATTLE, WA 98108</b>	VISTA ID#:	5377873
		Distance/Direction:	0.22 MI / NE
		Plotted as:	Point

Map ID  
**7**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>	Agency ID:	5289
--	------------	------

Agency Address:		EVERCLEAN WASH 551 S MICHIGAN ST SEATTLE, WA 98108	
Tank Status:		NOT AVAILABLE	
Discovery Date:		JUNE 8, 1994	
Media Affected:		SOIL/LAND/SAND	
Substance:		NOT AVAILABLE	
Leak Cause:		UNAVAILABLE	
Leak Source:		NOT AVAILABLE	
Remedial Action:		NOT AVAILABLE	
Remedial Status 1:		CLEANUP IN PROGRESS/REQUIRED	
Remedial Status 2:		NOT AVAILABLE	
Fields Not Reported:		Quantity (Units)	


<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>	Agency ID:	5289
---	------------	------

Agency Address:		EVERCLEAN WASH 551 S MICHIGAN ST SEATTLE, WA 98108	
Underground Tanks:		4	
Aboveground Tanks:		NOT REPORTED	
Tanks Removed:		NOT REPORTED	

Tank ID:	2U	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	UNLEADED GAS	Leak Monitoring:	NOT AVAILABLE
Tank Age:	19	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)	Tank Material:	STEEL

Tank ID:	2U	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	UNLEADED GAS	Leak Monitoring:	NOT AVAILABLE
Tank Age:	19	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)	Tank Material:	STEEL

Tank ID:	2U	Tank Status:	ACTIVE/IN SERVICE
Tank Contents:	UNLEADED GAS	Leak Monitoring:	NOT AVAILABLE
Tank Age:	19	Tank Piping:	NOT AVAILABLE
Tank Size (Units):	NOT REPORTED (NOT AVAILABLE)	Tank Material:	STEEL



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #19



**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>Tank ID:</b>	2U	<b>Tank Status:</b>	ACTIVE/IN SERVICE
<b>Tank Contents:</b>	LEADED GAS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	19	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL

<b>VISTA Address*:</b>	<b>GAS N WASH 551 S MICHIGAN ST SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1849624
		<b>Distance/Direction:</b>	0.22 MI / NE
		<b>Plotted as:</b>	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b>	<b>2761</b>	<b>Agency ID:</b>	5281

Map ID

**7**

<b>Agency Address:</b>	SAME AS ABOVE
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	JUNE 8, 1994
<b>Media Affected:</b>	SOIL/LAND/SAND
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)

<b>WA Toxics - Washington Toxics / SRC# 4061</b>	<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	GAS N WASH 551 S. MICHIGAN ST. SEATTLE, WA 98108	
<b>Region:</b>	NORTHWEST	
<b>State Detail Description:</b>	NO	
<b>Contact:</b>	NOT REPORTED	
<b>Description:</b>	WASTE:PETROLEUM PRODUCT	
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT:6/13/94 0:00:00	
<b>Description:</b>	MEDIA:SOIL	
<b>Description:</b>	REPORT TYPE:INTERIM	
<b>Description:</b>	ISSUE OF SITE REGISTER:93-30	

<b>WA Toxics - Washington Toxics / SRC# 4061</b>	<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	GAS-N-WASH 551 S. MICHIGAN ST. SEATTLE, WA 98108	
<b>Region:</b>	NORTHWEST	
<b>State Detail Description:</b>	NO	
<b>Contact:</b>	NOT REPORTED	
<b>Description:</b>	WASTE:PETROLEUM PRODUCT	
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT:10/23/95 0:00:00	
<b>Description:</b>	MEDIA:GROUNDWATER	
<b>Description:</b>	MEDIA:SOIL	
<b>Description:</b>	REPORT TYPE:INTERIM	
<b>Description:</b>	ISSUE OF SITE REGISTER:94-15	

\*VISTA address includes enhanced city and ZIP.


For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #20



**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>VISTA Address*:</b>	<b>SEAFREEZE LIMITED PARTNERSHIP 210 SW MICHIGAN PO BOX 24978 SEATTLE, WA 98124</b>		<b>VISTA ID#:</b>	1845959
			<b>Distance/Direction:</b>	0.22 MI / SW
			<b>Plotted as:</b>	Point
			<b>Agency ID:</b>	666
<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>				
<b>Agency Address:</b>		SAME AS ABOVE		
<b>Underground Tanks:</b>		1		
<b>Aboveground Tanks:</b>		NOT REPORTED		
<b>Tanks Removed:</b>		1		
<b>Tank ID:</b>	2U	<b>Tank Status:</b>	REMOVED	
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE	
<b>Tank Age:</b>	19	<b>Tank Piping:</b>	NOT AVAILABLE	
<b>Tank Size (Units):</b>	1100 (GALLONS)	<b>Tank Material:</b>	STEEL	

Map ID


**8A**

<b>VISTA Address*:</b>	<b>ALASKA MARINE LINES 2ND AVE SW 7100 2ND AVENUE SW SEATTLE, WA 98106</b>		<b>VISTA ID#:</b>	9996
			<b>Distance/Direction:</b>	0.24 MI / SW
			<b>Plotted as:</b>	Point
			<b>Agency ID:</b>	4131
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>				
<b>Agency Address:</b>		SAME AS ABOVE		
<b>Tank Status:</b>		NOT AVAILABLE		
<b>Discovery Date:</b>		DECEMBER 14, 1992		
<b>Media Affected:</b>		GROUNDWATER, SOIL		
<b>Substance:</b>		NOT AVAILABLE		
<b>Leak Cause:</b>		UNAVAILABLE		
<b>Leak Source:</b>		NOT AVAILABLE		
<b>Remedial Action:</b>		NOT AVAILABLE		
<b>Remedial Status 1:</b>		CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>		NOT AVAILABLE		
<b>Fields Not Reported:</b>		Quantity (Units)		

Map ID

**8B**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>Agency ID:</b>	100532
<b>Agency Address:</b>		ALASKA MARINE LINES (SHIPYARD) 7100 2ND AVENUE SW SEATTLE, WA 00009	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		DECEMBER 14, 1992	
<b>Media Affected:</b>		SOIL/LAND/SAND	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CLEANUP IN PROGRESS/REQUIRED	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Date of Report: January 2, 1998

Version 2.5

Page #21

**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	ALASKA MARINE LINES INC 7100 2ND AVE SW SEATTLE, WA 98106		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	DECEMBER 14, 1992		
<b>Media Affected:</b>	GROUNDWATER		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		
<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>		<b>Agency ID:</b>	100532
<b>Agency Address:</b>	ALASKA MARINE LINES (SHIPYARD) 7100 2ND AVENUE SW SEATTLE, WA 98106		
<b>Underground Tanks:</b>	2		
<b>Aboveground Tanks:</b>	NOT REPORTED		
<b>Tanks Removed:</b>	2		
<b>Tank ID:</b>	1U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	NOT AVAILABLE
<b>Tank ID:</b>	2U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	LEADED GAS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	NOT AVAILABLE



**\*VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5


Page #22

**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>VISTA Address*:</b>	<b>GREAT WESTERN CHEMICAL CO</b> <b>6900 FOX AVE</b> <b>SEATTLE, WA 98105</b>	<b>VISTA ID#:</b>	<b>179431</b>
		<b>Distance/Direction:</b>	<b>0.24 MI / SE</b>
		<b>Plotted as:</b>	<b>Point</b>
<b>NFRAP / SRC# 3860</b>		<b>EPA ID:</b>	<b>WAD008957961</b>
<b>Agency Address:</b>	SAME AS ABOVE		
<b>EPA Region:</b>	10		
<b>Congressional District:</b>	1		
<b>Federal Facility:</b>	NOT A FEDERAL FACILITY		
<b>Facility Ownership:</b>	UNKNOWN		
<b>Site Incident Category:</b>	unknown		
<b>Federal Facility Docket:</b>	SITE IS NOT INCLUDED ON THE DOCKET		
<b>NPL Status:</b>	NOT ON NPL		
<b>Incident Type:</b>	Unknown		
<b>Proposed NPL Update #:</b>	0		
<b>Final NPL Update #:</b>	0		
<b>Financial Management System ID:</b>	NOT REPORTED		
<b>Latitude:</b>	4732300		
<b>Longitude:</b>	12219400		
<b>Lat/Long Source:</b>	RESEARCHED BY THE REGION AND MANUALLY ENTERED		
<b>Lat/Long Accuracy:</b>	Unknown		
<b>Dioxin Tier:</b>	Unknown		
<b>USGS Hydro Unit:</b>	17110012		
<b>RCRA Indicator:</b>	ENVIRONMENTAL PRIORITY INITIATIVE		
<b>Unit Id:</b>	0		
<b>Unit Name:</b>	ENTIRE SITE		
<b>Type:</b>	DISCOVERY	<b>Lead Agency:</b>	
<b>Qualifier:</b>	UNKNOWN	<b>Category:</b>	Unknown
<b>Name:</b>	DISCOVERY	<b>Actual Start Date:</b>	NOT REPORTED
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN
<b>Type:</b>	PRELIMINARY ASSESSMENT	<b>Lead Agency:</b>	
<b>Qualifier:</b>	DEFERRED TO RCRA (SUBTITLE C) OR NRC	<b>Category:</b>	Unknown
<b>Name:</b>	PRELIMINARY ASSESSMENT	<b>Actual Start Date:</b>	UNKNOWN
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN

Map ID

**9**



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #23



**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

**CORRACTS / SRC# 3946**

**EPA ID:**

**WAD008957961**

<b>Agency Address:</b>	GREAT WESTERN CHEMICAL CO SEATTLE 6900 FOX AVE S SEATTLE, WA 98108
<b>Prioritization Status:</b>	LOW
<b>RCRA Facility Assessment Completed:</b>	YES
<b>Notice of Contamination:</b>	NO
<b>Determination of need For a RFI (RCRA Facility Investigation):</b>	YES
<b>RFI Imposed:</b>	NO
<b>RFI Workplan Notice of Deficiency Issued:</b>	NO
<b>RFI Workplan Approved:</b>	NO
<b>RFI Report Received:</b>	NO
<b>RFI Approved:</b>	NO
<b>No Further Corrective Action at this Time:</b>	YES
<b>Stabilization Mesasures Evaluation:</b>	NO
<b>CMS (Corrective Measure Study) Imposition:</b>	NO
<b>CMS Workplan Approved:</b>	NO
<b>CMS Report Received:</b>	NO
<b>CMS Approved:</b>	NO
<b>Date for Remedy Selection (CM Imposed):</b>	NO
<b>Corrective Measures Design Approved:</b>	NO
<b>Corrective Measures Investigation Workplan Approved:</b>	NO
<b>Certification of Remedy Completion:</b>	NO
<b>Stabilization Measures Implementation:</b>	NO
<b>Stabilization Measures Completed:</b>	NO
<b>Corrective Action Process Termination:</b>	NO

**STATE LUST - State Leaking Underground Storage Tank / SRC# 4113**

**Agency ID:**

**3803**

<b>Agency Address:</b>	GREATWESTERN CHEMICAL 6900 FOX AVE. SOUTH SEATTLE, WA 98108
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	MAY 17, 1990
<b>Media Affected:</b>	SOIL/LAND/SAND
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)

**\* VISTA address includes enhanced city and ZIP.**


For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #24



**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>VISTA Address*:</b>	<b>GREAT WESTERN CHEMICAL</b> <b>6900 FOX AV S</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	6959837
		<b>Distance/Direction:</b>	0.24 MI / SE
		<b>Plotted as:</b>	Point
<b>SPL - State Equivalent Priority List / SRC# 4060</b>		<b>Agency ID:</b>	2282 WARM 1
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	REMEDIAL ACTION IN PROGRESS		
<b>Pollutant 1:</b>	HALOGENATED ORGANIC COMPOUNDS		
<b>Pollutant 2:</b>	PETROLEUM		
<b>Pollutant 3:</b>	SOLVENTS		


Map ID  
**9**

<b>VISTA Address*:</b>	<b>GREAT WESTERN CHEMICAL CO</b> <b>6900 FOX AVE. SOUTH</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1844645
		<b>Distance/Direction:</b>	0.24 MI / SE
		<b>Plotted as:</b>	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		<b>Agency ID:</b>	1819
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	MAY 17, 1990		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		

Map ID  
**9**

<b>WA Toxics - Washington Toxics / SRC# 4061</b>		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	GREAT WESTERN CHEMICAL 6900 FOX AVE. SOUTH SEATTLE, WA 98108		
<b>Region:</b>	NORTHWEST		
<b>State Detail Description:</b>	NO		
<b>Contact:</b>	NOT REPORTED		
<b>Description:</b>	WASTE:HALOGENATED ORGANIC COMPOUNDS		
<b>Description:</b>	WASTE:PETROLEUM PRODUCT		
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT:7/16/90 0:00:00		
<b>Description:</b>	MEDIA:SOIL		
<b>Description:</b>	REPORT TYPE:INTERIM		
<b>Description:</b>	ISSUE OF SITE REGISTER:90-07		

<b>STATE UST - State Underground Storage Tank / SRC# 4114</b>		<b>Agency ID:</b>	3803
<b>Agency Address:</b>	GREATWESTERN CHEMICAL 6900 FOX AVE. SOUTH SEATTLE, WA 98108		
<b>Underground Tanks:</b>	26		
<b>Aboveground Tanks:</b>	NOT REPORTED		
<b>Tanks Removed:</b>	20		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.  
Report ID: 153929-001


Version 2.5

Date of Report: January 2, 1998

Page #25

**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>Tank ID:</b>	1U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	2U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	3U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	4U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	5U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	6U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	7U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	8U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	9U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	10U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	11U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Date of Report: January 2, 1998

Version 2.5

Page #26

**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>Tank ID:</b>	12U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	13U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	14U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	15U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	16U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	17U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	18U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	19U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	20U	<b>Tank Status:</b>	REMOVED
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	33	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	21U	<b>Tank Status:</b>	TEMP OUT OF SERVICE
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	41	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	22U	<b>Tank Status:</b>	TEMP OUT OF SERVICE
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	41	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #27



**SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile) CONT.**

<b>Tank ID:</b>	23U	<b>Tank Status:</b>	TEMP OUT OF SERVICE
<b>Tank Contents:</b>	OTHER	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	41	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	24U	<b>Tank Status:</b>	TEMP OUT OF SERVICE
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	41	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	25U	<b>Tank Status:</b>	TEMP OUT OF SERVICE
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	41	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL
<b>Tank ID:</b>	26U	<b>Tank Status:</b>	TEMP OUT OF SERVICE
<b>Tank Contents:</b>	HAZARDOUS	<b>Leak Monitoring:</b>	NOT AVAILABLE
<b>Tank Age:</b>	41	<b>Tank Piping:</b>	NOT AVAILABLE
<b>Tank Size (Units):</b>	NOT REPORTED (NOT AVAILABLE)	<b>Tank Material:</b>	STEEL

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)**


<b>VISTA Address*:</b>	<b>CONSOLIDATED FREIGHTWAYS 6050 E MARGINAL WAY S SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	97635
		<b>Distance/Direction:</b>	0.27 MI / N
		<b>Plotted as:</b>	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b>	2761	<b>Agency ID:</b>	2626

Map ID

**10**

<b>Agency Address:</b>	SAME AS ABOVE
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	JUNE 2, 1988
<b>Media Affected:</b>	GROUNDWATER, SOIL
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)

<b>WA Toxics - Washington Toxics / SRC#</b>	4061	<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	CONSOLIDATED FREIGHTWAYS (TWO REPORTS) 6050 E. MARGINAL WAY S. SEATTLE, WA 98108		
<b>Region:</b>	NORTHWEST		
<b>State Detail Description:</b>	NO		
<b>Contact:</b>	NOT REPORTED		
<b>Description:</b>	WASTE: PETROLEUM PRODUCT		
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT: 5/12/97 0:00:00		
<b>Description:</b>	MEDIA: GROUNDWATER		
<b>Description:</b>	MEDIA: SOIL		
<b>Description:</b>	REPORT TYPE: INTERIM		
<b>Description:</b>	ISSUE OF SITE REGISTER: 94-53		



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #28

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113	<b>Agency ID:</b>	11012
---	-------------------	-------

<b>Agency Address:</b>	SAME AS ABOVE
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	JUNE 2, 1988
<b>Media Affected:</b>	SOIL/LAND/SAND
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113	<b>EPA/Agency ID:</b>	N/A
---	-----------------------	-----

<b>Agency Address:</b>	SAME AS ABOVE
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	JUNE 2, 1988
<b>Media Affected:</b>	GROUNDWATER
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)

<b>VISTA Address*:</b>	<b>EMERALD TOOL INC</b> <b>6332 6TH S</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	3270552
		<b>Distance/Direction:</b>	0.29 MI / E
		<b>Plotted as:</b>	Point
<b>NFRAP / SRC# 3860</b>		<b>EPA ID:</b>	WAD042476788

Map ID

**11**


<b>Agency Address:</b>	SAME AS ABOVE		
<b>Alias Name:</b>	AND ALL ELECTRO CHROME, INC.		
<b>Alias Street:</b>	NOT REPORTED		
<b>Alias City:</b>	NOT REPORTED	<b>Alias Latitude:</b>	0
<b>Alias Zip:</b>	NOT REPORTED	<b>Alias Longitude:</b>	0
<b>Alias State:</b>	NOT REPORTED		
<b>Alias Description:</b>	NOT REPORTED		

\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.  
Report ID: 153929-001

Date of Report: January 2, 1998  
Page #29

Version 2.5



# SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.

EPA Region:	10		
Congressional District:	7		
Federal Facility:	NOT A FEDERAL FACILITY		
Facility Ownership:	OTHER		
Site Incident Category:	unknown		
Federal Facility Docket:	SITE IS NOT INCLUDED ON THE DOCKET		
NPL Status:	NOT ON NPL		
Incident Type:	Unknown		
Proposed NPL Update #:	0		
Final NPL Update #:	0		
Financial Management System ID:	NOT REPORTED		
Latitude:	4732430		
Longitude:	12219420		
Lat/Long Source:	RESEARCHED BY THE REGION AND MANUALLY ENTERED		
Lat/Long Accuracy:	Unknown		
Dioxin Tier:	Unknown		
USGS Hydro Unit:	17110013		
RCRA Indicator:	Unknown		
Unit Id:	0		
Unit Name:	ENTIRE SITE		
Type:	DISCOVERY	Lead Agency:	
Qualifier:	UNKNOWN	Category:	Unknown
Name:	DISCOVERY	Actual Start Date:	NOT REPORTED
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN
Type:	PRELIMINARY ASSESSMENT	Lead Agency:	
Qualifier:	HIGHER PRIORITY	Category:	Unknown
Name:	PRELIMINARY ASSESSMENT	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN
Type:	SCREENING SITE INSPECTION	Lead Agency:	
Qualifier:	NO FURTHER REMEDIAL ACTION PLANNED	Category:	Unknown
Name:	SCREENING SITE INSPECTION	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN

VISTA Address*:	AND ALL ELECTROCHROME INC 6332 6TH S SEATTLE, WA 98108	VISTA ID#:	84
		Distance/Direction:	0.30 MI / E
		Plotted as:	Point
SPL - State Equivalent Priority List / SRC# 4060		Agency ID:	2084 WARM 5

Map ID

11

Agency Address:	SAME AS ABOVE
Status:	UNKNOWN
Facility Type:	NOT AVAILABLE
Lead Agency:	NOT AVAILABLE
State Status:	RANKED, AWAITING REMEDIAL ACTION (RA)
Pollutant 1:	HALOGENATED ORGANIC COMPOUNDS
Pollutant 2:	EPA PRIORITY POLLUTANTS-METALS CYANIDE
Pollutant 3:	SOLVENTS

\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #30

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

Map ID


**11**

VISTA Address*:	<b>TEXACO STATION # 63 232 1455</b> <b>600 S MICHIGAN</b> <b>SEATTLE, WA 98108</b>	VISTA ID#:	5731939
		Distance/Direction:	0.32 MI / NE
		Plotted as:	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		Agency ID:	309690

Agency Address:	SAME AS ABOVE
Tank Status:	NOT AVAILABLE
Discovery Date:	MARCH 23, 1994
Media Affected:	GROUNDWATER, SOIL
Substance:	NOT AVAILABLE
Leak Cause:	UNAVAILABLE
Leak Source:	NOT AVAILABLE
Remedial Action:	NOT AVAILABLE
Remedial Status 1:	REM ACTION PENDING
Remedial Status 2:	NOT AVAILABLE
Fields Not Reported:	Quantity (Units)

<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	TEXACO #63 232 1455 (TWO REPORTS) 600 S. MICHIGAN SEATTLE, WA 98108		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE: PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT: 5/6/97 0:00:00		
Description:	MEDIA: GROUNDWATER		
Description:	MEDIA: SOIL		
Description:	REPORT TYPE: INTERIM		
Description:	ISSUE OF SITE REGISTER: 95-01		

<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	TEXACO #63 232 1455 600 S. MICHIGAN SEATTLE, WA 98108		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE: PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT: 5/1/97 0:00:00		
Description:	MEDIA: GROUNDWATER		
Description:	MEDIA: SOIL		
Description:	REPORT TYPE: INTERIM		
Description:	ISSUE OF SITE REGISTER: 95-01		



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Version 2.5

Date of Report: January 2, 1998

Page #31

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>Agency ID:</b>	4487
<b>Agency Address:</b>	TEXACO #63-232-1455 600 S MICHIGAN SEATTLE, WA 98108		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	MARCH 23, 1994		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	TEXACO STATION # 63 232 1455 600 S MICHIGAN SEATTLE, WA 98108-2633		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	MARCH 23, 1994		
<b>Media Affected:</b>	GROUNDWATER		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	TEXACO STATION # 63 232 1455 600 S MICHIGAN SEATTLE, WA 98108-2633		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	MARCH 23, 1994		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	REM ACTION PENDING		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #32



**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	TEXACO STATION # 63 232 1455 600 S MICHIGAN SEATTLE, WA 98108-2633		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	MARCH 23, 1994		
<b>Media Affected:</b>	GROUNDWATER		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	REM ACTION PENDING		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		

<b>VISTA Address*:</b>	<b>PENINSULA TRUCK LINES</b> 6314 7TH S SEATTLE, WA 98108	<b>VISTA ID#:</b>	324077
		<b>Distance/Direction:</b>	0.35 MI / E
		<b>Plotted as:</b>	Point

Map ID

**11**


<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 2761		<b>Agency ID:</b>	1579
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	AUGUST 29, 1989		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		

<b>VISTA Address*:</b>	<b>PTL PARTNERSHIP</b> 6314 7TH S SEATTLE, WA 98108	<b>VISTA ID#:</b>	1841830
		<b>Distance/Direction:</b>	0.35 MI / E
		<b>Plotted as:</b>	Point

Map ID

**11**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>Agency ID:</b>	25
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	AUGUST 29, 1989		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5


Page #33

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>VISTA Address*:</b>	<b>LONE STAR (CONCRETE) NW 5975 E MARGINAL WAY S SEATTLE, WA 98134</b>	<b>VISTA ID#:</b>	<b>4267290</b>
		<b>Distance/Direction:</b>	<b>0.35 MI / N</b>
		<b>Plotted as:</b>	<b>Point</b>
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		<b>Agency ID:</b>	<b>1365</b>
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		JUNE 1, 1989	
<b>Media Affected:</b>		SURFACE WATER SOIL/LAND/SAND	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CLEANUP IN PROGRESS/REQUIRED	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>Agency ID:</b>	<b>2211</b>
<b>Agency Address:</b>		LONE STAR NORTHWEST, INC. 5975 E MARGINAL WAY S SEATTLE, WA 98134	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		JUNE 1, 1989	
<b>Media Affected:</b>		SURFACE WATER	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CLEANUP IN PROGRESS/REQUIRED	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>EPA/Agency ID:</b>	<b>N/A</b>
<b>Agency Address:</b>		LONE STAR (CONCRETE) NW 5975 E. MARGINAL WAY SOUT SEATTLE, WA 98134-2414	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		JUNE 1, 1989	
<b>Media Affected:</b>		SOIL/LAND/SAND	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CLEANUP IN PROGRESS/REQUIRED	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	

Map ID

**12**



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #34

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>VISTA Address*:</b>	<b>CHEVRON USA INC SS 90636</b>	<b>VISTA ID#:</b>	<b>81774</b>
	<b>590 E MARGINAL WAY</b>	<b>Distance/Direction:</b>	<b>0.37 MI / N.</b>
	<b>SEATTLE, WA 98134</b>	<b>Plotted as:</b>	<b>Point</b>
	<b>WA Toxics - Washington Toxics / SRC# 4061</b>	<b>EPA/Agency ID:</b>	<b>N/A</b>

Map ID

**12**

<b>Agency Address:</b>	CHEVRON #0636 5940 E. MARGINAL WAY SEATTLE, WA 98134
<b>Region:</b>	NORTHWEST
<b>State Detail Description:</b>	NO
<b>Contact:</b>	NOT REPORTED
<b>Description:</b>	WASTE:PETROLEUM PRODUCT
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT: 8/16/96 0:00:00
<b>Description:</b>	MEDIA:SOIL
<b>Description:</b>	REPORT TYPE:INTERIM
<b>Description:</b>	ISSUE OF SITE REGISTER:94-38

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>	<b>Agency ID:</b>	<b>5061</b>
--	-------------------	-------------


<b>Agency Address:</b>	CHEVRON 0636 5940 E MARGINAL WAY SEATTLE, WA 98134
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	NOVEMBER 9, 1993
<b>Media Affected:</b>	SOIL/LAND/SAND
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	REM ACTION PENDING
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)

<b>VISTA Address*:</b>	<b>JAMES HARDIE GYPSUM</b>	<b>VISTA ID#:</b>	<b>187277</b>
	<b>5931 E. MARGINAL WAY SO.</b>	<b>Distance/Direction:</b>	<b>0.37 MI / N</b>
	<b>SEATTLE, WA 98134</b>	<b>Plotted as:</b>	<b>Point</b>
	<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>	<b>Agency ID:</b>	<b>1903</b>

Map ID

**12**

<b>Agency Address:</b>	SAME AS ABOVE
<b>Tank Status:</b>	NOT AVAILABLE
<b>Discovery Date:</b>	JANUARY 11, 1991
<b>Media Affected:</b>	SOIL/LAND/SAND
<b>Substance:</b>	NOT AVAILABLE
<b>Leak Cause:</b>	UNAVAILABLE
<b>Leak Source:</b>	NOT AVAILABLE
<b>Remedial Action:</b>	NOT AVAILABLE
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED
<b>Remedial Status 2:</b>	NOT AVAILABLE
<b>Fields Not Reported:</b>	Quantity (Units)



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Version 2.5

Date of Report: January 2, 1998

Page #35

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	<b>2253 WARM</b>
<b>Agency Address:</b>	JAMES HARDIE GYPSUM 5931 E MARGINAL WY S SEATTLE, WA 98134		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	INDEPENDENT REMEDIAL ACTION, INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV		
<b>Pollutant 1:</b>	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
<b>Pollutant 2:</b>	UNKNOWN		
<b>Pollutant 3:</b>	UNKNOWN		
<b>WA Toxics - Washington Toxics / SRC# 4061</b>		<b>EPA/Agency ID:</b>	<b>N/A</b>
<b>Agency Address:</b>	JAMES HARDIE GYPSUM 5931 E. MARGINAL WAY S. SEATTLE, WA 98134		
<b>Region:</b>	NORTHWEST		
<b>State Detail Description:</b>	NO		
<b>Contact:</b>	NOT REPORTED		
<b>Description:</b>	WASTE: METALS		
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT: 7/24/91 0:00:00		
<b>Description:</b>	MEDIA: GROUNDWATER		
<b>Description:</b>	MEDIA: SOIL		
<b>Description:</b>	REPORT TYPE: INTERIM		
<b>Description:</b>	ISSUE OF SITE REGISTER: 92-05		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>Agency ID:</b>	<b>7095</b>
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	JANUARY 11, 1991		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		



**\*VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #36

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

Map ID

**12**

VISTA Address*:	<b>LONGVIEW FIBRE COMPANY 5901 EAST MARGINAL WAY SOUTH SEATTLE, WA 98134</b>	VISTA ID#:	249440
		Distance/Direction:	0.39 MI / N
		Plotted as:	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		Agency ID:	3449

**Agency Address:** SAME AS ABOVE  
**Tank Status:** NOT AVAILABLE  
**Discovery Date:** JANUARY 1, 1988  
**Media Affected:** SOIL/LAND/SAND  
**Substance:** NOT AVAILABLE  
**Leak Cause:** UNAVAILABLE  
**Leak Source:** NOT AVAILABLE  
**Remedial Action:** NOT AVAILABLE  
**Remedial Status 1:** CLEANUP IN PROGRESS/REQUIRED  
**Remedial Status 2:** NOT AVAILABLE  
**Fields Not Reported:** Quantity (Units)

<b>SPL - State Equivalent Priority List / SRC# 4060</b>	Agency ID:	2226 WARM 5
---	------------	-------------


**Agency Address:** LONGVIEW FIBRE CO  
 5901 E MARGINAL WY S  
 SEATTLE, WA 98134  
**Status:** UNKNOWN  
**Facility Type:** NOT AVAILABLE  
**Lead Agency:** NOT AVAILABLE  
**State Status:** INDEPENDENT REMEDIAL ACTION  
**Pollutant 1:** BASE/NEUTRAL/ACID ORGANICS  
**Pollutant 2:** PETROLEUM  
**Pollutant 3:** PAH

<b>WA Toxics - Washington Toxics / SRC# 4061</b>	EPA/Agency ID:	N/A
--	----------------	-----

**Agency Address:** LONGVIEW FIBER CO.  
 5901 E. MARGINAL WAY S.  
 SEATTLE, WA 98134  
**Region:** NORTHWEST  
**State Detail Description:** NO  
**Contact:** NOT REPORTED  
**Description:** WASTE:PETROLEUM PRODUCT  
**Description:** DATE ECOLOGY RECEIVED REPORT:11/1/96 0:00:00  
**Description:** MEDIA:GROUNDWATER  
**Description:** MEDIA:SOIL  
**Description:** REPORT TYPE:INTERIM  
**Description:** ISSUE OF SITE REGISTER:94-22

<b>WA Toxics - Washington Toxics / SRC# 4061</b>	EPA/Agency ID:	N/A
--	----------------	-----

**Agency Address:** LONGVIEW FIBRE CO.  
 5901 E. MARGINAL WAY S.  
 SEATTLE, WA 98134  
**Region:** NORTHWEST  
**State Detail Description:** NO  
**Contact:** NOT REPORTED  
**Description:** WASTE:PETROLEUM PRODUCT  
**Description:** DATE ECOLOGY RECEIVED REPORT:2/5/96 0:00:00  
**Description:** MEDIA:GROUNDWATER  
**Description:** MEDIA:SOIL  
**Description:** REPORT TYPE:INTERIM



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #37



**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**


Description:	ISSUE OF SITE REGISTER:94-24
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:2/9/90 0:00:00
Description:	MEDIA:SOIL
Description:	REPORT TYPE:FINAL
Description:	ISSUE OF SITE REGISTER:94-46

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113	<b>Agency ID:</b>	7348
<b>Agency Address:</b>	SAME AS ABOVE	
<b>Tank Status:</b>	NOT AVAILABLE	
<b>Discovery Date:</b>	JANUARY 1, 1988	
<b>Media Affected:</b>	SOIL/LAND/SAND	
<b>Substance:</b>	NOT AVAILABLE	
<b>Leak Cause:</b>	UNAVAILABLE	
<b>Leak Source:</b>	NOT AVAILABLE	
<b>Remedial Action:</b>	NOT AVAILABLE	
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED	
<b>Remedial Status 2:</b>	NOT AVAILABLE	
<b>Fields Not Reported:</b>	Quantity (Units)	

<b>VISTA Address*:</b>	<b>JONES WASHINGTON STEVEDORING</b> <b>7245 W.MARGINAL WAY S.W.</b> <b>SEATTLE, WA 98106</b>	<b>VISTA ID#:</b>	1846655
		<b>Distance/Direction:</b>	0.38 MI / SW
		<b>Plotted as:</b>	Point

Map ID  
**13**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 2761	<b>Agency ID:</b>	5592
<b>Agency Address:</b>	SAME AS ABOVE	
<b>Tank Status:</b>	NOT AVAILABLE	
<b>Discovery Date:</b>	OCTOBER 10, 1994	
<b>Media Affected:</b>	SOIL/LAND/SAND	
<b>Substance:</b>	NOT AVAILABLE	
<b>Leak Cause:</b>	UNAVAILABLE	
<b>Leak Source:</b>	NOT AVAILABLE	
<b>Remedial Action:</b>	NOT AVAILABLE	
<b>Remedial Status 1:</b>	CASE CLOSED/CLEANUP COMPLETE	
<b>Remedial Status 2:</b>	NOT AVAILABLE	
<b>Fields Not Reported:</b>	Quantity (Units)	



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #38

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>Agency ID:</b>	2313
<b>Agency Address:</b>		JONES WASHINGTON STEVEDORING CO. 7245 W. MARGINAL WAY S.W. SEATTLE, WA 98106	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		OCTOBER 10, 1994	
<b>Media Affected:</b>		SOIL/LAND/SAND	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CASE CLOSED/CLEANUP COMPLETE	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	


<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>		JONES WASHINGTON STEVEDORING CO. 7245 W. MARGINAL WAY S.W. SEATTLE, WA 98106	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		OCTOBER 10, 1994	
<b>Media Affected:</b>		SOIL/LAND/SAND	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CLEANUP IN PROGRESS/REQUIRED	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	

<b>VISTA Address*:</b>	<b>DNR CORSON - 6655; 6715; 6737 CORSON 6737 CORSON AVENUE SOUTH SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1854465
		<b>Distance/Direction:</b>	0.39 MI / E
		<b>Plotted as:</b>	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 2761		<b>Agency ID:</b>	1848

<b>Agency Address:</b>		SAME AS ABOVE	
<b>Tank Status:</b>		NOT AVAILABLE	
<b>Discovery Date:</b>		JUNE 11, 1990	
<b>Media Affected:</b>		SOIL/LAND/SAND	
<b>Substance:</b>		NOT AVAILABLE	
<b>Leak Cause:</b>		UNAVAILABLE	
<b>Leak Source:</b>		NOT AVAILABLE	
<b>Remedial Action:</b>		NOT AVAILABLE	
<b>Remedial Status 1:</b>		CASE CLOSED/CLEANUP COMPLETE	
<b>Remedial Status 2:</b>		NOT AVAILABLE	
<b>Fields Not Reported:</b>		Quantity (Units)	

Map ID

**14**



**\*VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #39

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>VISTA Address*:</b>	<b>ARROW TRANSPORTATION 6737 CORSON S SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	<b>209546</b>
		<b>Distance/Direction:</b>	<b>0.39 MI / E</b>
		<b>Plotted as:</b>	<b>Point</b>
<b>NFRAP / SRC# 3860</b>		<b>EPA ID:</b>	<b>WAD007942733</b>
<b>Agency Address:</b>	SAME AS ABOVE		
<b>EPA Region:</b>	10		
<b>Congressional District:</b>	7		
<b>Federal Facility:</b>	NOT A FEDERAL FACILITY		
<b>Facility Ownership:</b>	OTHER		
<b>Site Incident Category:</b>	unknown		
<b>Federal Facility Docket:</b>	SITE IS NOT INCLUDED ON THE DOCKET		
<b>NPL Status:</b>	NOT ON NPL		
<b>Incident Type:</b>	Unknown		
<b>Proposed NPL Update #:</b>	0		
<b>Final NPL Update #:</b>	0		
<b>Financial Management System ID:</b>	NOT REPORTED		
<b>Latitude:</b>	4732320		
<b>Longitude:</b>	12219240		
<b>Lat/Long Source:</b>	RESEARCHED BY THE REGION AND MANUALLY ENTERED		
<b>Lat/Long Accuracy:</b>	Unknown		
<b>Dioxin Tier:</b>	Unknown		
<b>USGS Hydro Unit:</b>	17110013		
<b>RCRA Indicator:</b>	Unknown		
<b>Unit Id:</b>	0		
<b>Unit Name:</b>	ENTIRE SITE		
<b>Type:</b>	DISCOVERY	<b>Lead Agency:</b>	
<b>Qualifier:</b>	UNKNOWN	<b>Category:</b>	Unknown
<b>Name:</b>	DISCOVERY	<b>Actual Start Date:</b>	NOT REPORTED
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN
<b>Type:</b>	PRELIMINARY ASSESSMENT	<b>Lead Agency:</b>	
<b>Qualifier:</b>	LOWER PRIORITY	<b>Category:</b>	Unknown
<b>Name:</b>	PRELIMINARY ASSESSMENT	<b>Actual Start Date:</b>	UNKNOWN
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN
<b>Type:</b>	SCREENING SITE INSPECTION	<b>Lead Agency:</b>	
<b>Qualifier:</b>	HIGHER PRIORITY	<b>Category:</b>	Unknown
<b>Name:</b>	SCREENING SITE INSPECTION	<b>Actual Start Date:</b>	UNKNOWN
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN
<b>Type:</b>	SCREENING SITE INSPECTION	<b>Lead Agency:</b>	
<b>Qualifier:</b>	NO FURTHER REMEDIAL ACTION PLANNED	<b>Category:</b>	Unknown
<b>Name:</b>	SCREENING SITE INSPECTION	<b>Actual Start Date:</b>	UNKNOWN
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN

Map ID

**14**

\* VISTA address includes enhanced city and ZIP.


For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998


Version 2.5

Page #40



**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2134 WARM
<b>Agency Address:</b>	INLAND TRANSPORTATION CO 6737 CORSON S SEATTLE, WA 98108		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	AWAITING SITE HAZARD ASSESSMENT (SHA)		
<b>Pollutant 1:</b>	HALOGENATED ORGANIC COMPOUNDS		
<b>Pollutant 2:</b>	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
<b>Pollutant 3:</b>	METALS OTHER		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>Agency ID:</b>	1940
<b>Agency Address:</b>	ARROW TRANSPORTATION COMPANY 6737 CORSON AVENUE SOUTH SEATTLE, WA 98108		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	JUNE 11, 1990		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CASE CLOSED/CLEANUP COMPLETE		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	INLAND TRANSPORTATION CO INC 6737 CORSON AVE S SEATTLE, WA 98108		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	JUNE 11, 1990		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #41

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>VISTA Address*:</b>	<b>SUNSET DISPOSAL 7201 W MARGINAL WAY SW SEATTLE, WA 98146</b>	<b>VISTA ID#:</b>	5749840
		<b>Distance/Direction:</b>	0.39 MI / SW
		<b>Plotted as:</b>	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>Agency ID:</b>	3446

Map ID

**15**

**Agency Address:** SAME AS ABOVE  
**Tank Status:** NOT AVAILABLE  
**Discovery Date:** APRIL 30, 1992  
**Media Affected:** SOIL/LAND/SAND  
**Substance:** NOT AVAILABLE  
**Leak Cause:** UNAVAILABLE  
**Leak Source:** NOT AVAILABLE  
**Remedial Action:** NOT AVAILABLE  
**Remedial Status 1:** CLEANUP IN PROGRESS/REQUIRED  
**Remedial Status 2:** NOT AVAILABLE  
**Fields Not Reported:** Quantity (Units)

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>	<b>EPA/Agency ID:</b>	N/A
--	-----------------------	-----


**Agency Address:** SAME AS ABOVE  
**Tank Status:** NOT AVAILABLE  
**Discovery Date:** APRIL 30, 1992  
**Media Affected:** GROUNDWATER  
**Substance:** NOT AVAILABLE  
**Leak Cause:** UNAVAILABLE  
**Leak Source:** NOT AVAILABLE  
**Remedial Action:** NOT AVAILABLE  
**Remedial Status 1:** CLEANUP IN PROGRESS/REQUIRED  
**Remedial Status 2:** NOT AVAILABLE  
**Fields Not Reported:** Quantity (Units)

<b>VISTA Address*:</b>	<b>WASTE MANAGEMENT SEATTLE 7201 W MARGINAL WAY SW SEATTLE, WA 98146</b>	<b>VISTA ID#:</b>	40433
		<b>Distance/Direction:</b>	0.39 MI / SW
		<b>Plotted as:</b>	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		<b>Agency ID:</b>	3644

Map ID

**15**

**Agency Address:** SAME AS ABOVE  
**Tank Status:** NOT AVAILABLE  
**Discovery Date:** APRIL 30, 1992  
**Media Affected:** GROUNDWATER, SOIL  
**Substance:** NOT AVAILABLE  
**Leak Cause:** UNAVAILABLE  
**Leak Source:** NOT AVAILABLE  
**Remedial Action:** NOT AVAILABLE  
**Remedial Status 1:** CLEANUP IN PROGRESS/REQUIRED  
**Remedial Status 2:** NOT AVAILABLE  
**Fields Not Reported:** Quantity (Units)



**\*VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #42



**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2425 WARM
Agency Address:	WASTE MANAGEMENT OF SEATTLE 7201 W MARGINAL WAY SW SEATTLE, WA 98106		
Status:	UNKNOWN		
Facility Type:	NOT AVAILABLE		
Lead Agency:	NOT AVAILABLE		
State Status:	AWAITING SITE HAZARD ASSESSMENT (SHA)		
Pollutant 1:	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
Pollutant 2:	PETROLEUM		
Pollutant 3:	UNKNOWN		

<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	WASTE MANAGEMENT - SEATTLE 7201 W. MARGINAL WAY SW SEATTLE, WA 98106		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:92-30		

VISTA Address*:	<b>BAYSIDE DISPOSAL CO</b> <b>7201 W MARGINAL WAY S</b> <b>SEATTLE, WA 98106</b>	VISTA ID#:	3509044
		Distance/Direction:	0.39 MI / SW
		Plotted as:	Point

Map ID

**15**

<b>NFRAP / SRC# 3860</b>		EPA ID:	WAD980723084
Agency Address:	SAME AS ABOVE		
Alias Name:	SUNSET DISPOSAL		
Alias Street:	NOT REPORTED		
Alias City:	NOT REPORTED	Alias Latitude:	0
Alias Zip:	NOT REPORTED	Alias Longitude:	0
Alias State:	NOT REPORTED		
Alias Description:	NOT REPORTED		

**\* VISTA address includes enhanced city and ZIP.**


For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998


Version 2.5

Page #43



**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>EPA Region:</b>	10
<b>Congressional District:</b>	7
<b>Federal Facility:</b>	NOT A FEDERAL FACILITY
<b>Facility Ownership:</b>	OTHER
<b>Site Incident Category:</b>	unknown
<b>Federal Facility Docket:</b>	SITE IS NOT INCLUDED ON THE DOCKET
<b>NPL Status:</b>	NOT ON NPL
<b>Incident Type:</b>	Unknown
<b>Proposed NPL Update #:</b>	0
<b>Final NPL Update #:</b>	0
<b>Financial Management System ID:</b>	NOT REPORTED
<b>Latitude:</b>	4732200
<b>Longitude:</b>	12219110
<b>Lat/Long Source:</b>	RESEARCHED BY THE REGION AND MANUALLY ENTERED
<b>Lat/Long Accuracy:</b>	Unknown
<b>Dioxin Tier:</b>	Unknown
<b>USGS Hydro Unit:</b>	17110013
<b>RCRA Indicator:</b>	Unknown
<b>Unit Id:</b>	0
<b>Unit Name:</b>	ENTIRE SITE
<b>Type:</b>	DISCOVERY
<b>Qualifier:</b>	UNKNOWN
<b>Name:</b>	DISCOVERY
<b>Plan Status:</b>	Unknown
<b>Lead Agency:</b>	Unknown
<b>Category:</b>	Unknown
<b>Actual Start Date:</b>	NOT REPORTED
<b>Actual Completion Date:</b>	UNKNOWN
<b>Type:</b>	PRELIMINARY ASSESSMENT
<b>Qualifier:</b>	NO FURTHER REMEDIAL ACTION PLANNED
<b>Name:</b>	PRELIMINARY ASSESSMENT
<b>Plan Status:</b>	Unknown
<b>Lead Agency:</b>	Unknown
<b>Category:</b>	Unknown
<b>Actual Start Date:</b>	UNKNOWN
<b>Actual Completion Date:</b>	UNKNOWN
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>	
<b>Agency Address:</b>	BAYSIDE DISPOSAL CO 7201 W MARGINAL WY SW SEATTLE, WA 98106
<b>Status:</b>	UNKNOWN
<b>Facility Type:</b>	NOT AVAILABLE
<b>Lead Agency:</b>	NOT AVAILABLE
<b>State Status:</b>	AWAITING SITE HAZARD ASSESSMENT (SHA)
<b>Pollutant 1:</b>	PETROLEUM
<b>Pollutant 2:</b>	SOLVENTS
<b>Pollutant 3:</b>	UNKNOWN



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #44

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

VISTA Address*:	<b>WASTE MANAGEMENT OF SEATTLE WA</b>	VISTA ID#:	4287932
		Distance/Direction:	0.39 MI / SW
		Plotted as:	Point
<b>STATE SWLF - Solid Waste Landfill / SRC# 2764</b>		Agency ID:	NKW2
Agency Address:		SAME AS ABOVE	
Facility Type:		RESOURCE RECOVERY (RECYCLING)	
Facility Status:		NOT AVAILABLE	
Facility Life:		NOT REPORTED	
Permit Status:		NOT AVAILABLE	
Waste:		NOT REPORTED	

Map ID

**15**


VISTA Address*:	<b>BEN'S TRUCK PARTS 6655 CORSON AVENUE SOUTH SEATTLE, WA 98108</b>	VISTA ID#:	6782638
		Distance/Direction:	0.40 MI / E
		Plotted as:	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		Agency ID:	396593

Map ID

**16**

Agency Address:		SAME AS ABOVE	
Tank Status:		NOT AVAILABLE	
Discovery Date:		JUNE 11, 1990	
Media Affected:		SOIL/LAND/SAND	
Substance:		NOT AVAILABLE	
Leak Cause:		UNAVAILABLE	
Leak Source:		NOT AVAILABLE	
Remedial Action:		NOT AVAILABLE	
Remedial Status 1:		CLEANUP IN PROGRESS/REQUIRED	
Remedial Status 2:		NOT AVAILABLE	
Fields Not Reported:		Quantity (Units)	

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		EPA/Agency ID:	N/A
Agency Address:		BEN'S TRUCK PARTS 6655 CORSON AVENUE SOUTH SEATTLE, WA 98108-3447	
Tank Status:		NOT AVAILABLE	
Discovery Date:		JUNE 11, 1990	
Media Affected:		GROUNDWATER	
Substance:		NOT AVAILABLE	
Leak Cause:		UNAVAILABLE	
Leak Source:		NOT AVAILABLE	
Remedial Action:		NOT AVAILABLE	
Remedial Status 1:		CLEANUP IN PROGRESS/REQUIRED	
Remedial Status 2:		NOT AVAILABLE	
Fields Not Reported:		Quantity (Units)	



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #45

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

VISTA Address*:	<b>SAHLBERG EQUIPMENT 5950 4TH AV S SEATTLE, WA 98108</b>	VISTA ID#:	4917627
		Distance/Direction:	0.41 MI / NE
		Plotted as:	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2450 WARM

Map ID

**17**

<b>Agency Address:</b>	SAME AS ABOVE
<b>Status:</b>	UNKNOWN
<b>Facility Type:</b>	NOT AVAILABLE
<b>Lead Agency:</b>	NOT AVAILABLE
<b>State Status:</b>	INDEPENDENT REMEDIAL ACTION, INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV
<b>Pollutant 1:</b>	HALOGENATED ORGANIC COMPOUNDS
<b>Pollutant 2:</b>	PETROLEUM
<b>Pollutant 3:</b>	UNKNOWN


<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
<b>Agency Address:</b>	SAHLBERG EQUIPMENT 5950 4TH AVE. S. SEATTLE, WA 98108		
<b>Region:</b>	NORTHWEST		
<b>State Detail Description:</b>	NO		
<b>Contact:</b>	NOT REPORTED		
<b>Description:</b>	WASTE: TOTAL PETROLEUM HYDROCARBONS		
<b>Description:</b>	WASTE: HALOGENATED SOLVENTS		
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT: 7/21/93 0:00:00		
<b>Description:</b>	MEDIA: SOIL		
<b>Description:</b>	REPORT TYPE: INTERIM		
<b>Description:</b>	ISSUE OF SITE REGISTER: 93-07		

VISTA Address*:	<b>MOBILE CRANE AKA WESTERN BRIDGE CO 5900 SECOND AVE SO SEATTLE, WA 98108</b>	VISTA ID#:	5377772
		Distance/Direction:	0.42 MI / N
		Plotted as:	Point

Map ID

**18**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		Agency ID:	5685
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	MARCH 1, 1995		
<b>Media Affected:</b>	GROUNDWATER, SOIL		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	REM ACTION PENDING		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #46

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

VISTA Address*:	<b>WESTERN BRIDGE CO 5900 SECOND AVE SO SEATTLE, WA 98108</b>	VISTA ID#:	1840743
		Distance/Direction:	0.45 MI / N
		Plotted as:	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		Agency ID:	10209

Map ID  
**18**

Agency Address: SAME AS ABOVE  
 Tank Status: NOT AVAILABLE  
 Discovery Date: MARCH 1, 1995  
 Media Affected: SOIL/LAND/SAND  
 Substance: NOT AVAILABLE  
 Leak Cause: UNAVAILABLE  
 Leak Source: NOT AVAILABLE  
 Remedial Action: NOT AVAILABLE  
 Remedial Status 1: REM ACTION PENDING  
 Remedial Status 2: NOT AVAILABLE  
 Fields Not Reported: Quantity (Units)


<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>	EPA/Agency ID:	N/A
--	----------------	-----

Agency Address: SAME AS ABOVE  
 Tank Status: NOT AVAILABLE  
 Discovery Date: MARCH 1, 1995  
 Media Affected: GROUNDWATER  
 Substance: NOT AVAILABLE  
 Leak Cause: UNAVAILABLE  
 Leak Source: NOT AVAILABLE  
 Remedial Action: NOT AVAILABLE  
 Remedial Status 1: REM ACTION PENDING  
 Remedial Status 2: NOT AVAILABLE  
 Fields Not Reported: Quantity (Units)

VISTA Address*:	<b>EASTMONT TRANSFER STATION 7155 W MARGINAL WY SW SEATTLE, WA 98106</b>	VISTA ID#:	5165444
		Distance/Direction:	0.43 MI / W
		Plotted as:	Point
<b>STATE SWLF - Solid Waste Landfill / SRC# 2764</b>		Agency ID:	NKE1

Map ID  
**19**

Agency Address: SAME AS ABOVE  
 Facility Type: TRANSFER STATION  
 Facility Status: NOT AVAILABLE  
 Facility Life: NOT REPORTED  
 Permit Status: NOT AVAILABLE  
 Waste: MUNICIPAL SOLID WASTE  
 Waste: CONSTRUCTION/DEMO  
 Waste: ASBESTOS  
 Waste: PETROLEUM  
 Waste: OTHER



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #47


**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

VISTA Address*:	<b>SEATTLE, CY OF, 1ST AV BRG LDFL E MARGINAL WY S FIDALGO ST SEATTLE, WA 98108</b>		VISTA ID#:	373103
			Distance/Direction:	0.44 MI / N
			Plotted as:	Point
<b>NFRAP / SRC# 3860</b>			EPA ID:	WAD980975197
<b>Agency Address:</b>		SAME AS ABOVE		
<b>Site Description:</b>		WEST OF EAST MARGINAL WAY SOUTH AND FIDALGO ST. A VACENT LOTNEXTTO THE OLD GYPSUM CO BUILDING.		
<b>EPA Region:</b>		10		
<b>Congressional District:</b>		7		
<b>Federal Facility:</b>		NOT A FEDERAL FACILITY		
<b>Facility Ownership:</b>		OTHER		
<b>Site Incident Category:</b>		unknown		
<b>Federal Facility Docket:</b>		SITE IS NOT INCLUDED ON THE DOCKET		
<b>NPL Status:</b>		NOT ON NPL		
<b>Incident Type:</b>		Unknown		
<b>Proposed NPL Update #:</b>		0		
<b>Final NPL Update #:</b>		0		
<b>Financial Management System ID:</b>		NOT REPORTED		
<b>Latitude:</b>		4733020		
<b>Longitude:</b>		12220020		
<b>Lat/Long Source:</b>		RESEARCHED BY THE REGION AND MANUALLY ENTERED		
<b>Lat/Long Accuracy:</b>		Unknown		
<b>Dioxin Tier:</b>		Unknown		
<b>USGS Hydro Unit:</b>		17110013		
<b>RCRA Indicator:</b>		Unknown		
<b>Unit Id:</b>		0		
<b>Unit Name:</b>		ENTIRE SITE		
<b>Type:</b>	PRELIMINARY ASSESSMENT	<b>Lead Agency:</b>		
<b>Qualifier:</b>	NO FURTHER REMEDIAL ACTION PLANNED	<b>Category:</b>	Unknown	
<b>Name:</b>	PRELIMINARY ASSESSMENT	<b>Actual Start Date:</b>	UNKNOWN	
<b>Plan Status:</b>	Unknown	<b>Actual Completion Date:</b>	UNKNOWN	

Map ID  
**20**

VISTA Address*:	<b>INCON PACKAGING 5801 EAST MARGINAL WAY SOUTH SEATTLE, WA 98134</b>		VISTA ID#:	6607455
			Distance/Direction:	0.46 MI / N
			Plotted as:	Point
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>			Agency ID:	5333
<b>Agency Address:</b>		SAME AS ABOVE		
<b>Tank Status:</b>		NOT AVAILABLE		
<b>Discovery Date:</b>		DECEMBER 15, 1989		
<b>Media Affected:</b>		SOIL/LAND/SAND		
<b>Substance:</b>		NOT AVAILABLE		
<b>Leak Cause:</b>		UNAVAILABLE		
<b>Leak Source:</b>		NOT AVAILABLE		
<b>Remedial Action:</b>		NOT AVAILABLE		
<b>Remedial Status 1:</b>		CASE CLOSED/CLEANUP COMPLETE		
<b>Remedial Status 2:</b>		NOT AVAILABLE		
<b>Fields Not Reported:</b>		Quantity (Units)		

Map ID  
**20**



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #48



**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>EPA/Agency ID:</b>	N/A
<b>Agency Address:</b>	INCON PACKAGING 5801 EAST MARGINAL WAY SOUTH SEATTLE, WA 98134-2413		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	DECEMBER 15, 1989		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		

<b>VISTA Address*:</b>	<b>WDOT CORSON</b> <b>6431 CORSON AVE S</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1856056
		<b>Distance/Direction:</b>	0.46 MI / E
		<b>Plotted as:</b>	Point

Map ID

**21**


<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 2761		<b>Agency ID:</b>	2165
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	APRIL 17, 1991		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	UNKNOWN		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		

<b>VISTA Address*:</b>	<b>DISTRICT HEADQUARTERS SITE</b> <b>6431 CORSON AVE S</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	1843513
		<b>Distance/Direction:</b>	0.46 MI / E
		<b>Plotted as:</b>	Point

Map ID

**21**

<b>STATE LUST - State Leaking Underground Storage Tank / SRC#</b> 4113		<b>Agency ID:</b>	12241
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	APRIL 17, 1991		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	UNKNOWN		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #49

**SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.**

<b>VISTA Address*:</b>	<b>FERGUSON CONSTRUCTION</b> <b>7433 5TH AVE S</b> <b>SEATTLE, WA</b>	<b>VISTA ID#:</b>	<b>1853579</b>
		<b>Distance/Direction:</b>	<b>0.47 MI / SE</b>
		<b>Plotted as:</b>	<b>Point</b>
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 2761</b>		<b>Agency ID:</b>	<b>2146</b>
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	NOVEMBER 13, 1990		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		
<b>WA Toxics - Washington Toxics / SRC# 4061</b>		<b>EPA/Agency ID:</b>	<b>N/A</b>
<b>Agency Address:</b>	FERGUSON CONSTRUCTION (TWO REPORTS) 7433 FIFTH AVE. S. SEATTLE, WA 98108		
<b>Region:</b>	NORTHWEST		
<b>State Detail Description:</b>	NO		
<b>Contact:</b>	NOT REPORTED		
<b>Description:</b>	WASTE:PETROLEUM PRODUCT		
<b>Description:</b>	DATE ECOLOGY RECEIVED REPORT:9/20/94 0:00:00		
<b>Description:</b>	MEDIA:GROUNDWATER		
<b>Description:</b>	MEDIA:SOIL		
<b>Description:</b>	REPORT TYPE:INTERIM		
<b>Description:</b>	ISSUE OF SITE REGISTER:95-04		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		<b>Agency ID:</b>	<b>200658</b>
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Tank Status:</b>	NOT AVAILABLE		
<b>Discovery Date:</b>	NOVEMBER 13, 1990		
<b>Media Affected:</b>	SOIL/LAND/SAND		
<b>Substance:</b>	NOT AVAILABLE		
<b>Leak Cause:</b>	UNAVAILABLE		
<b>Leak Source:</b>	NOT AVAILABLE		
<b>Remedial Action:</b>	NOT AVAILABLE		
<b>Remedial Status 1:</b>	CLEANUP IN PROGRESS/REQUIRED		
<b>Remedial Status 2:</b>	NOT AVAILABLE		
<b>Fields Not Reported:</b>	Quantity (Units)		

Map ID

**22**

**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.  
Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #50

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)**

VISTA Address*:	<b>BOEING NORTH FIELD ELLIS AV E MARGINAL WY SEATTLE, WA 98108</b>	VISTA ID#:	6783364
		Distance/Direction:	0.57 MI / E
		Plotted as:	Point
<b>SPL - State Equivalent Priority List / SRC# 4060</b>		Agency ID:	2050 WARM 5
Agency Address:		SAME AS ABOVE	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		INDEPENDENT REMEDIAL ACTION, INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV	
Pollutant 1:		HALOGENATED ORGANIC COMPOUNDS	
Pollutant 2:		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
Pollutant 3:		METALS OTHER	

Map ID

**23**

VISTA Address*:	<b>BOEING NORTH FIELD JP4 TANKS ELLIS AV E MARGINAL WY SEATTLE, WA 98108</b>	VISTA ID#:	6783140
		Distance/Direction:	0.58 MI / E
		Plotted as:	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2053 WARM
Agency Address:		SAME AS ABOVE	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		AWAITING SITE HAZARD ASSESSMENT (SHA)	
Pollutant 1:		PETROLEUM	
Pollutant 2:		UNKNOWN	
Pollutant 3:		UNKNOWN	


Map ID

**23**

VISTA Address*:	<b>STERNOFF METALS 7201 E MARGINAL WAY S SEATTLE, WA 98108</b>	VISTA ID#:	399610
		Distance/Direction:	0.59 MI / E
		Plotted as:	Point
<b>SPL - State Equivalent Priority List / SRC# 4060</b>		Agency ID:	2057 WARM 5
Agency Address:		STERNOFF METALS 7201 E MARGINAL WY S SEATTLE, WA 98108	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		INDEPENDENT REMEDIAL ACTION	
Pollutant 1:		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
Pollutant 2:		PCB'S	
Pollutant 3:		UNKNOWN	

Map ID

**23**



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #51

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

VISTA Address*:	<b>FIRST AV BRIDGE LANDFILL 7700 BLOCK OF 2ND AV SW SEATTLE, WA 98106</b>	VISTA ID#:	1854090
		Distance/Direction:	0.62 MI / S
		Plotted as:	Point

Map ID

**24**

**SCL - State Equivalent CERCLIS List / SRC# 4059**

Agency ID:	2201 WARM
------------	-----------

Agency Address:	SAME AS ABOVE
Status:	UNKNOWN
Facility Type:	NOT AVAILABLE
Lead Agency:	NOT AVAILABLE
State Status:	AWAITING SITE HAZARD ASSESSMENT (SHA)
Pollutant 1:	CONVENTIONAL CONTAMINANTS, ORGANIC
Pollutant 2:	UNKNOWN
Pollutant 3:	UNKNOWN

VISTA Address*:	<b>EASTERN SUPPLY CO 7745 1ST AV S SEATTLE, WA 98108</b>	VISTA ID#:	2882786
		Distance/Direction:	0.62 MI / S
		Plotted as:	Point

Map ID

**24**

**SPL - State Equivalent Priority List / SRC# 4060**

Agency ID:	2258 WARM 2
------------	-------------

Agency Address:	SAME AS ABOVE
Status:	UNKNOWN
Facility Type:	NOT AVAILABLE
Lead Agency:	NOT AVAILABLE
State Status:	REMEDIAL ACTION IN PROGRESS
Pollutant 1:	HALOGENATED ORGANIC COMPOUNDS
Pollutant 2:	UNKNOWN
Pollutant 3:	UNKNOWN

VISTA Address*:	<b>WEST COAST EQUIPMENT INC 7777 DETROIT AV SW SEATTLE, WA 98106</b>	VISTA ID#:	1854572
		Distance/Direction:	0.64 MI / SW
		Plotted as:	Point


Map ID

**25**

**SCL - State Equivalent CERCLIS List / SRC# 4059**

Agency ID:	2262 WARM
------------	-----------

Agency Address:	SAME AS ABOVE
Status:	UNKNOWN
Facility Type:	NOT AVAILABLE
Lead Agency:	NOT AVAILABLE
State Status:	AWAITING SITE HAZARD ASSESSMENT (SHA)
Pollutant 1:	HALOGENATED ORGANIC COMPOUNDS
Pollutant 2:	PETROLEUM
Pollutant 3:	SOLVENTS



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #52

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

<b>VISTA Address*:</b>	<b>MASTER BUILDERS 64 S LUCILE ST SEATTLE, WA 98134</b>	<b>VISTA ID#:</b>	1855279
		<b>Distance/Direction:</b>	0.66 MI / N
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2254 WARM
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		AWAITING SITE HAZARD ASSESSMENT (SHA)	
<b>Pollutant 1:</b>		HALOGENATED ORGANIC COMPOUNDS	
<b>Pollutant 2:</b>		PETROLEUM	
<b>Pollutant 3:</b>		SOLVENTS	

Map ID

**26**

<b>VISTA Address*:</b>	<b>MST CHEMICALS INC 6020 W MARGINAL SW SEATTLE, WA 98106</b>	<b>VISTA ID#:</b>	1855689
		<b>Distance/Direction:</b>	0.67 MI / NW
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2177 WARM
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		AWAITING SITE HAZARD ASSESSMENT (SHA)	
<b>Pollutant 1:</b>		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
<b>Pollutant 2:</b>		METALS OTHER	
<b>Pollutant 3:</b>		CORROSIVE WASTES	


Map ID

**27**

<b>VISTA Address*:</b>	<b>REICHOLD CHEMICAL LONE STAR 5900 W MARGINAL WAY SW SEATTLE, WA 98106</b>	<b>VISTA ID#:</b>	2884087
		<b>Distance/Direction:</b>	0.71 MI / NW
		<b>Plotted as:</b>	Point
<b>SPL - State Equivalent Priority List / SRC# 4060</b>		<b>Agency ID:</b>	2167 WARM 1
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		RANKED, AWAITING REMEDIAL ACTION (RA)	
<b>Pollutant 1:</b>		HALOGENATED ORGANIC COMPOUNDS	
<b>Pollutant 2:</b>		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
<b>Pollutant 3:</b>		PETROLEUM	

Map ID

**27**



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #53

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

<b>VISTA Address*:</b>	<b>SEATTLE COMMERCIAL FINISHING 5700 CORSON AV S SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	2820
		<b>Distance/Direction:</b>	0.72 MI / NE
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2309 WARM
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		AWAITING SITE HAZARD ASSESSMENT (SHA)	
<b>Pollutant 1:</b>		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
<b>Pollutant 2:</b>		PAH	
<b>Pollutant 3:</b>		CONVENTIONAL CONTAMINANTS, INORGANIC	

Map ID

**28**

<b>VISTA Address*:</b>	<b>SEATTLE S TRANSFER STA 8100 2ND AV S SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	6959767
		<b>Distance/Direction:</b>	0.73 MI / S
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2175 WARM
<b>Agency Address:</b>		SAME AS ABOVE	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		INDEPENDENT REMEDIAL ACTION, RELEASE RPT REC, AWAITING ASSESS BY PLP	
<b>Pollutant 1:</b>		CONVENTIONAL CONTAMINANTS, INORGANIC	
<b>Pollutant 2:</b>		CONVENTIONAL CONTAMINANTS, ORGANIC	
<b>Pollutant 3:</b>		UNKNOWN	


Map ID

**29**

<b>VISTA Address*:</b>	<b>INTERSTATE COATINGS INC 754 S CHICAGO ST SEATTLE, WA 981084321</b>	<b>VISTA ID#:</b>	537533
		<b>Distance/Direction:</b>	0.77 MI / SE
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2335 WARM
<b>Agency Address:</b>		INTERSTATE COATINGS 754 S CHICAGO SEATTLE, WA 98108	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		AWAITING SITE HAZARD ASSESSMENT (SHA)	
<b>Pollutant 1:</b>		HALOGENATED ORGANIC COMPOUNDS	
<b>Pollutant 2:</b>		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
<b>Pollutant 3:</b>		PETROLEUM	

Map ID

**30**



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #54



**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

VISTA Address*:	<b>BURL ENV INC DBA PHILIP ENV INC LUCILE 734 S LUCILE ST SEATTLE, WA 98108</b>	VISTA ID#:	6607395
		Distance/Direction:	0.79 MI / NE
		Plotted as:	Point

Map ID


**31**

<b>CORRACTS / SRC# 3946</b>	EPA ID:	WAD000812909
-----------------------------	---------	--------------

<b>Agency Address:</b>	SAME AS ABOVE
<b>Prioritization Status:</b>	MEDIUM
<b>RCRA Facility Assessment Completed:</b>	YES
<b>Notice of Contamination:</b>	NO
<b>Determination of need For a RFI (RCRA Facility Investigation):</b>	YES
<b>RFI Imposed:</b>	YES
<b>RFI Workplan Notice of Deficiency Issued:</b>	NO
<b>RFI Workplan Approved:</b>	YES
<b>RFI Report Received:</b>	NO
<b>RFI Approved:</b>	YES
<b>No Further Corrective Action at this Time:</b>	NO
<b>Stabilization Mesaures Evaluation:</b>	YES
<b>CMS (Corrective Measure Study) Imposition:</b>	NO
<b>CMS Workplan Approved:</b>	NO
<b>CMS Report Received:</b>	NO
<b>CMS Approved:</b>	NO
<b>Date for Remedy Selection (CM Imposed):</b>	NO
<b>Corrective Measures Design Approved:</b>	NO
<b>Corrective Measures Investigation Workplan Approved:</b>	NO
<b>Certification of Remedy Completion:</b>	NO
<b>Stabilization Measures Implementation:</b>	YES
<b>Stabilization Measures Completed:</b>	NO
<b>Corrective Action Process Termination:</b>	NO

<b>RCRA-TSD CORRACTS / SRC# 3946</b>	EPA ID:	WAD000812909
--------------------------------------	---------	--------------

<b>Agency Address:</b>	SAME AS ABOVE
<b>Off-Site Waste Received:</b>	YES
<b>Land Disposal:</b>	NO
<b>Incinerator:</b>	NO
<b>Storage/Treatment:</b>	YES



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #55

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

<b>VISTA Address*:</b>	<b>CHEMICAL PROCESSORS INC/LUCILE</b> <b>734 S LUCILE ST</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	79440
		<b>Distance/Direction:</b>	0.79 MI / NE
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2108 WARM
<b>Agency Address:</b>	SAME AS ABOVE		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	AWAITING SITE HAZARD ASSESSMENT (SHA)		
<b>Pollutant 1:</b>	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
<b>Pollutant 2:</b>	METALS OTHER		
<b>Pollutant 3:</b>	PESTICIDE		

Map ID

**31**

<b>VISTA Address*:</b>	<b>DUWAMISH SHIPYARD INC</b> <b>5658 W MARGINAL WAY SW</b> <b>SEATTLE, WA 981061596</b>	<b>VISTA ID#:</b>	130505
		<b>Distance/Direction:</b>	0.80 MI / NW
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2071 WARM
<b>Agency Address:</b>	DUWAMISH SHIPYARD INC 5658 W MARGINAL WY SW SEATTLE, WA 98106		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	INDEPENDENT REMEDIAL ACTION, INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV		
<b>Pollutant 1:</b>	PETROLEUM		
<b>Pollutant 2:</b>	UNKNOWN		
<b>Pollutant 3:</b>	UNKNOWN		


Map ID

**32**

<b>VISTA Address*:</b>	<b>WRIGHT SCHUCHART HARBOR CO</b> <b>SEATTLE</b> <b>5500 W MARGINAL WAY SW</b> <b>SEATTLE, WA 98106</b>	<b>VISTA ID#:</b>	475943
		<b>Distance/Direction:</b>	0.87 MI / NW
		<b>Plotted as:</b>	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	2339 WARM
<b>Agency Address:</b>	WRIGHT-SCHUCHART INC 5500 W MARGINAL WAY SW SEATTLE, WA 98106		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	AWAITING SITE HAZARD ASSESSMENT (SHA)		
<b>Pollutant 1:</b>	PETROLEUM		
<b>Pollutant 2:</b>	UNKNOWN		
<b>Pollutant 3:</b>	UNKNOWN		

Map ID

**32**



**\*VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #56

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

VISTA Address*:	<b>KING AUTO TRUCK WRECKING</b> <b>543 S MONROE</b> <b>SEATTLE, WA 98108</b>	VISTA ID#:	1855587
		Distance/Direction:	0.81 MI / SE
		Plotted as:	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2278 WARM
Agency Address:		SAME AS ABOVE	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		AWAITING SITE HAZARD ASSESSMENT (SHA)	
Pollutant 1:		PETROLEUM	
Pollutant 2:		UNKNOWN	
Pollutant 3:		UNKNOWN	


Map ID

**33**

VISTA Address*:	<b>PIONEER ENAMEL MFG CO INC</b> <b>5531 AIRPORT WAY S</b> <b>SEATTLE, WA 98108</b>	VISTA ID#:	331364
		Distance/Direction:	0.81 MI / NE
		Plotted as:	Point
<b>SPL - State Equivalent Priority List / SRC# 4060</b>		Agency ID:	2161 WARM 5
Agency Address:		PIONEER ENAMEL MANUFACTURE 5531 AIRPORT WAY S SEATTLE, WA 98108	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		RANKED, AWAITING REMEDIAL ACTION (RA)	
Pollutant 1:		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
Pollutant 2:		UNKNOWN	
Pollutant 3:		UNKNOWN	

Map ID

**34**



**\*VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5


Page #57

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

Map ID

**35**

VISTA Address*:	<b>GENERAL ELECTRIC CO SEATTLE DAWSON 220 S DAWSON ST SEATTLE, WA 98108</b>	VISTA ID#:	167631
		Distance/Direction:	0.84 MI / N
		Plotted as:	Point
<b>CORRACTS / SRC# 3946</b>		EPA ID:	WAD009278706
Agency Address:		SAME AS ABOVE	
Prioritization Status:		HIGH	
RCRA Facility Assessment Completed:		YES	
Notice of Contamination:		NO	
Determination of need For a RFI (RCRA Facility Investigation):		YES	
RFI Imposed:		NO	
RFI Workplan Notice of Deficiency Issued:		NO	
RFI Workplan Approved:		NO	
RFI Report Received:		NO	
RFI Approved:		NO	
No Further Corrective Action at this Time:		NO	
Stabilization Mesaures Evaluation:		YES	
CMS (Corrective Measure Study) Imposition:		NO	
CMS Workplan Approved:		NO	
CMS Report Received:		NO	
CMS Approved:		NO	
Date for Remedy Selection (CM Imposed):		NO	
Corrective Measures Design Approved:		NO	
Corrective Measures Investigation Workplan Approved:		NO	
Certification of Remedy Completion:		NO	
Stabilization Measures Implementation:		NO	
Stabilization Measures Completed:		NO	
Corrective Action Process Termination:		NO	
<b>RCRA-TSD CORRACTS / SRC# 3946</b>		EPA ID:	WAD009278706
Agency Address:		SAME AS ABOVE	
Off-Site Waste Received:		NO	
Land Disposal:		NO	
Incinerator:		NO	
Storage/Treatment:		NO	



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #58

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

<b>SPL - State Equivalent Priority List / SRC# 4060</b>		<b>Agency ID:</b>	<b>2522 WARM 2</b>
<b>Agency Address:</b>	GENERAL ELEC AVIATION DAWSON 220 S DAWSON ST SEATTLE, WA 98108		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	REMEDIAL ACTION IN PROGRESS, RELEASE RPT REC, AWAITING ASSESS BY PLP		
<b>Pollutant 1:</b>	BASE/NEUTRAL/ACID ORGANICS		
<b>Pollutant 2:</b>	HALOGENATED ORGANIC COMPOUNDS		
<b>Pollutant 3:</b>	PETROLEUM		

<b>VISTA Address*:</b>	<b>NORTHWEST ENVIROSERVICE INC</b> <b>8105 1ST AVE S</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	<b>4071706</b>
		<b>Distance/Direction:</b>	<b>0.86 MI / S</b>
		<b>Plotted as:</b>	<b>Point</b>

Map ID

**36**


<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	<b>2536 WARM</b>
<b>Agency Address:</b>	NORTHWEST ENVIROSERVICE 2 8105 1ST AV S SEATTLE, WA 98108		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	INDEPENDENT REMEDIAL ACTION, INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV		
<b>Pollutant 1:</b>	HALOGENATED ORGANIC COMPOUNDS		
<b>Pollutant 2:</b>	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
<b>Pollutant 3:</b>	PETROLEUM		

<b>VISTA Address*:</b>	<b>PRESERVATIVE PAINT CO</b> <b>5410 AIRPORT WAY SOUTH</b> <b>SEATTLE, WA 98108</b>	<b>VISTA ID#:</b>	<b>338638</b>
		<b>Distance/Direction:</b>	<b>0.87 MI / NE</b>
		<b>Plotted as:</b>	<b>Point</b>

Map ID

**37**

<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		<b>Agency ID:</b>	<b>2163 WARM</b>
<b>Agency Address:</b>	PRESERVATIVE PAINT COMPANY 5410 AIRPORT WAY S SEATTLE, WA 98108		
<b>Status:</b>	UNKNOWN		
<b>Facility Type:</b>	NOT AVAILABLE		
<b>Lead Agency:</b>	NOT AVAILABLE		
<b>State Status:</b>	AWAITING SITE HAZARD ASSESSMENT (SHA)		
<b>Pollutant 1:</b>	HALOGENATED ORGANIC COMPOUNDS		
<b>Pollutant 2:</b>	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
<b>Pollutant 3:</b>	PETROLEUM		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #59

**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

VISTA Address*:	<b>CRAIG TAYLOR EQUIPMENT</b> <b>5030 1ST AVE S</b> <b>SEATTLE, WA</b>	VISTA ID#:	1852533
		Distance/Direction:	0.89 MI / N
		Plotted as:	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2363 WARM
Agency Address:		CRAIG TAYLOR EQUIPMENT 5030 1ST AV S SEATTLE, WA 98134	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		AWAITING SITE HAZARD ASSESSMENT (SHA)	
Pollutant 1:		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
Pollutant 2:		METALS OTHER	
Pollutant 3:		PETROLEUM	


Map ID  
**38**

VISTA Address*:	<b>MARINE VACUUM SVC INC</b> <b>1516 S GRAHAM ST</b> <b>SEATTLE, WA 98108</b>	VISTA ID#:	260641
		Distance/Direction:	0.94 MI / E
		Plotted as:	Point
<b>SPL - State Equivalent Priority List / SRC# 4060</b>		Agency ID:	2216 WARM 3
Agency Address:		MARINE VACUUM SERVICE INC 1516 S GRAHAM ST SEATTLE, WA 98108	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		RANKED, AWAITING REMEDIAL ACTION (RA)	
Pollutant 1:		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
Pollutant 2:		PETROLEUM	
Pollutant 3:		CONVENTIONAL CONTAMINANTS, INORGANIC	

Map ID  
**39**

VISTA Address*:	<b>NORTH COAST CHEMICAL</b> <b>6300 17TH AVE S</b> <b>SEATTLE, WA</b>	VISTA ID#:	299754
		Distance/Direction:	0.98 MI / E
		Plotted as:	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2153 WARM
Agency Address:		NORTH COAST CHEMICAL CO 6300 17TH AV S SEATTLE, WA 98108	
Status:		UNKNOWN	
Facility Type:		NOT AVAILABLE	
Lead Agency:		NOT AVAILABLE	
State Status:		INDEPENDENT REMEDIAL ACTION, RELEASE RPT REC, AWAITING ASSESS BY PLP	
Pollutant 1:		HALOGENATED ORGANIC COMPOUNDS	
Pollutant 2:		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
Pollutant 3:		PETROLEUM	

Map ID  
**39**



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #60




**SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.**

VISTA Address*:	<b>MANITOWOC WESTERN</b> <b>8250 5TH AVE S</b> <b>SEATTLE, WA 981084533</b>	VISTA ID#:	6499806
		Distance/Direction:	0.97 MI / S
		Plotted as:	Point
<b>SCL - State Equivalent CERCLIS List / SRC# 4059</b>		Agency ID:	2430 WARM
<b>Agency Address:</b>		MANITOWAK WESTERN 8250 5TH AV S SEATTLE, WA 98108	
<b>Status:</b>		UNKNOWN	
<b>Facility Type:</b>		NOT AVAILABLE	
<b>Lead Agency:</b>		NOT AVAILABLE	
<b>State Status:</b>		AWAITING SITE HAZARD ASSESSMENT (SHA)	
<b>Pollutant 1:</b>		EPA PRIORITY POLLUTANTS-METALS CYANIDE	
<b>Pollutant 2:</b>		PETROLEUM	
<b>Pollutant 3:</b>		UNKNOWN	

Map ID

**40**



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #61

# UNMAPPED SITES


VISTA Address*:	LIDLAW 7739 1ST AV S SEATTLE, WA 98108	VISTA ID#:	6959750
SPL - State Equivalent Priority List / SRC# 4060		Agency ID:	2320 WARM 4
Agency Address:	SAME AS ABOVE		
Status:	UNKNOWN		
Facility Type:	NOT AVAILABLE		
Lead Agency:	NOT AVAILABLE		
State Status:	RANKED, AWAITING REMEDIAL ACTION (RA)		
Pollutant 1:	PHENOLIC COMPOUNDS		
Pollutant 2:	UNKNOWN		
Pollutant 3:	UNKNOWN		

VISTA Address*:	METRO POWER DISTRIBUTION HQ 2255 44TH AVE. S. SEATTLE, WA 98134	VISTA ID#:	6808295
WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:9/4/91 0:00:00		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:92-06		

VISTA Address*:	80TH S. HUDSON ST. 80TH S. HUDSON ST. SEATTLE, WA 98134	VISTA ID#:	6808378
WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:1/23/92 0:00:00		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:92-19		
WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	80TH S. HUDSON ST. (THREE REPORTS) 80TH S. HUDSON ST. SEATTLE, WA 98134		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:2/10/94 0:00:00		



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #62

# UNMAPPED SITES CONT.


Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:93-21

VISTA Address*:	NORTHWEST COOPERAGE CO., INC. 7152 1ST AVE. SOUTH SEATTLE, WA 98108	VISTA ID#:	6808193
-----------------	---	------------	---------

WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:HALOGENATED ORGANIC COMPOUNDS		
Description:	WASTE:METALS		
Description:	WASTE:POLYCHLORINATED BIPHENYLS		
Description:	WASTE:PESTICIDES		
Description:	WASTE:PHENOLIC COMPOUNDS		
Description:	WASTE:NON-HALOGENATED SOLVENTS		
Description:	WASTE:POLYNUCLEAR AROMATIC HYDROCARBONS		
Description:	DATE ECOLOGY RECEIVED REPORT:10/7/91 0:00:00		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:92-08		

VISTA Address*:	TERMINAL 30 PORT OF SEATTLE SEATTLE, WA 98134	VISTA ID#:	6807976
-----------------	---	------------	---------

WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:90-11		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #63

# UNMAPPED SITES CONT.

VISTA Address*:	SW HARBOR PROJ WYCKOFF W MARGINAL WY SW FLORIDA ST SW SEATTLE, WA 98134	VISTA ID#:	6783416
-----------------	---	------------	---------

SCL - State Equivalent CERCLIS List / SRC# 4059		Agency ID:	2387 WARM
Agency Address:	SAME AS ABOVE		
Status:	UNKNOWN		
Facility Type:	NOT AVAILABLE		
Lead Agency:	NOT AVAILABLE		
State Status:	REMEDIAL ACTION IN PROGRESS		
Pollutant 1:	EPA PRIORITY POLLUTANTS-METALS CYANIDE		
Pollutant 2:	PCB'S		
Pollutant 3:	PAH		

VISTA Address*:	TERMINAL 18 PORT OF SEATTLE SEATTLE, WA 98134	VISTA ID#:	6807975
-----------------	---	------------	---------


WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:90-11		

VISTA Address*:	TERMINAL 106 PORT OF SEATTLE SEATTLE, WA 98134	VISTA ID#:	6807974
-----------------	--	------------	---------

WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:90-11		

VISTA Address*:	HORTON ST. MAINTENANCE SHOP PORT OF SEATTLE SEATTLE, WA 98134	VISTA ID#:	6807973
-----------------	---	------------	---------

WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #64

# UNMAPPED SITES CONT.

Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:90-11

VISTA Address*:	PUGET PARK 16TH AV SW SEATTLE, WA 98106
-----------------	---

VISTA ID#:	6959760
------------	---------

SCL - State Equivalent CERCLIS List / SRC# 4059

Agency ID:	2479 WARM
------------	-----------

Agency Address:	SAME AS ABOVE
Status:	UNKNOWN
Facility Type:	NOT AVAILABLE
Lead Agency:	NOT AVAILABLE
State Status:	INDEPENDENT REMEDIAL ACTION,INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV
Pollutant 1:	EPA PRIORITY POLLUTANTS-METALS CYANIDE
Pollutant 2:	UNKNOWN
Pollutant 3:	UNKNOWN

VISTA Address*:	KING CO - SOUTHPARK LDFL S PARK, W OF 5TH AV S ROSE SEATTLE, WA 98106
-----------------	---

VISTA ID#:	229386
------------	--------

NFRAP / SRC# 3860

EPA ID:	WAD980511596
---------	--------------

Agency Address:	SAME AS ABOVE		
Alias Name:	SOUTHPARK LANDFILL		
Alias Street:	NOT REPORTED		
Alias City:	NOT REPORTED	Alias Latitude:	0
Alias Zip:	NOT REPORTED	Alias Longitude:	0
Alias State:	NOT REPORTED		
Alias Description:	NOT REPORTED		
EPA Region:	10		
Congressional District:	7		
Federal Facility:	NOT A FEDERAL FACILITY		
Facility Ownership:	OTHER		
Site Incident Category:	unknown		
Federal Facility Docket:	SITE IS NOT INCLUDED ON THE DOCKET		
NPL Status:	NOT ON NPL		
Incident Type:	Unknown		
Proposed NPL Update #:	0		
Final NPL Update #:	0		
Financial Management System ID:	NOT REPORTED		
Latitude:	4731450		
Longitude:	12219500		
Lat/Long Source:	RESEARCHED BY THE REGION AND MANUALLY ENTERED		
Lat/Long Accuracy:	Unknown		
Dioxin Tier:	Unknown		
USGS Hydro Unit:	17110013		
RCRA Indicator:	Unknown		

\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5


Page #65

# UNMAPPED SITES CONT.

Unit Id:	0		
Unit Name:	ENTIRE SITE		
Type:	DISCOVERY	Lead Agency:	
Qualifier:	UNKNOWN	Category:	Unknown
Name:	DISCOVERY	Actual Start Date:	NOT REPORTED
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN
Type:	PRELIMINARY ASSESSMENT	Lead Agency:	
Qualifier:	LOWER PRIORITY	Category:	Unknown
Name:	PRELIMINARY ASSESSMENT	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN
Type:	SCREENING SITE INSPECTION	Lead Agency:	
Qualifier:	HIGHER PRIORITY	Category:	Unknown
Name:	SCREENING SITE INSPECTION	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN
Type:	SCREENING SITE INSPECTION	Lead Agency:	
Qualifier:	NO FURTHER REMEDIAL ACTION PLANNED	Category:	Unknown
Name:	SCREENING SITE INSPECTION	Actual Start Date:	UNKNOWN
Plan Status:	Unknown	Actual Completion Date:	UNKNOWN

VISTA Address*:	MELTON'S HEATING TANK 17767 15TH AVE. NW SEATTLE, WA 98108	VISTA ID#:	6808134
WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:10/14/92 0:00:00		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:92-35		

VISTA Address*:	SOUTHPARK LANDFILL S PARK SEATTLE, WA 98108	VISTA ID#:	6959924
SCL - State Equivalent CERCLIS List / SRC# 4059		Agency ID:	2180 WARM
Agency Address:	SAME AS ABOVE		
Status:	UNKNOWN		
Facility Type:	NOT AVAILABLE		
Lead Agency:	NOT AVAILABLE		
State Status:	AWAITING SITE HAZARD ASSESSMENT (SHA)		
Pollutant 1:	BASE/NEUTRAL/ACID ORGANICS		
Pollutant 2:	HALOGENATED ORGANIC COMPOUNDS		
Pollutant 3:	EPA PRIORITY POLLUTANTS-METALS CYANIDE		



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #66



**UNMAPED SITES CONT.**

VISTA Address*:	<b>BOEING - NORTH BOEING FIELD TRAINING FA KING COUNTY AIRPORT SEATTLE, WA 98108</b>	VISTA ID#:	5189276

<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:METALS		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	WASTE:NON-HALOGENATED SOLVENTS		
Description:	DATE ECOLOGY RECEIVED REPORT:12/21/92 0:00:00		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:92-40		


<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	BOEING - NORTH FIELD - FIRE TRAINING FA KING COUNTY AIRPORT SEATTLE, WA 98108		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:7/21/94 0:00:00		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:FINAL		
Description:	ISSUE OF SITE REGISTER:93-34		

VISTA Address*:	<b>BOW LAKE TRANSFER STATION 18800 ORILLIA RD S TUKWILA, WA</b>	VISTA ID#:	5165450

<b>STATE SWLF - Solid Waste Landfill / SRC# 2764</b>		Agency ID:	NKB2
Agency Address:	SAME AS ABOVE		
Facility Type:	TRANSFER STATION		
Facility Status:	NOT AVAILABLE		
Permit Status:	NOT AVAILABLE		

VISTA Address*:	<b>SEATAC AIRPORT - PAN AM HANGER PORT OF SEATTLE SEATTLE, WA 98108</b>	VISTA ID#:	6807969

<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	MEDIA:GROUNDWATER		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #67

# UNMAPPED SITES CONT.

Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:90-11

VISTA Address*:	NORTHWEST ENVIROSERVICE 2W 1ST AV SW MARGINAL SEATTLE, WA 98108	VISTA ID#:	6959874
-----------------	---	------------	---------

SCL - State Equivalent CERCLIS List / SRC# 4059	Agency ID:	2537 WARM
---	------------	-----------

Agency Address:	SAME AS ABOVE
Status:	UNKNOWN
Facility Type:	NOT AVAILABLE
Lead Agency:	NOT AVAILABLE
State Status:	INDEPENDENT REMEDIAL ACTION,INDEPENDENT SITE ASSESSMENT OR INTERIM RA RPT RECEIV
Pollutant 1:	HALOGENATED ORGANIC COMPOUNDS
Pollutant 2:	EPA PRIORITY POLLUTANTS-METALS CYANIDE
Pollutant 3:	PETROLEUM

VISTA Address*:	NORTHWEST ENVIRO SERVICE 1ST AVE. S. SEATTLE, WA 98108	VISTA ID#:	5411762
-----------------	--	------------	---------


WA Toxics - Washington Toxics / SRC# 4061	EPA/Agency ID:	N/A
---	----------------	-----

Agency Address:	SAME AS ABOVE
Region:	NORTHWEST
State Detail Description:	NO
Contact:	NOT REPORTED
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:11/18/94 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	MEDIA:SEDIMENTS
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:93-40

VISTA Address*:	BOEING FIELD - NORTH MAIN FUEL FARM SE OF BLDG 3-465 SEATTLE, WA 98108	VISTA ID#:	5412382
-----------------	--	------------	---------

WA Toxics - Washington Toxics / SRC# 4061	EPA/Agency ID:	N/A
---	----------------	-----

Agency Address:	SAME AS ABOVE
Region:	NORTHWEST
State Detail Description:	NO
Contact:	NOT REPORTED
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:1/18/95 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:93-45



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Version 2.5

Date of Report: January 2, 1998

Page #68

**UNMAPPED SITES CONT.**

VISTA Address*:	<b>SEATAC CRAWFORD AVIATION SEATAC INTERNATIONAL AIRPORT SEATAC, WA 98168</b>	VISTA ID#:	4686193
<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:11/4/93 0:00:00		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:FINAL		
Description:	ISSUE OF SITE REGISTER:93-13		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:11/4/93 0:00:00		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:93-13		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		Agency ID:	200557
Agency Address:	SEA-TAC CRAWFORD AVIATION SEA-TAC INTERNATIONAL AIRPORT SEATAC, WA		
Tank Status:	NOT AVAILABLE		
Discovery Date:	JUNE 22, 1993		
Media Affected:	SOIL/LAND/SAND		
Substance:	NOT AVAILABLE		
Remedial Action:	NOT AVAILABLE		
Remedial Status 1:	CASE CLOSED/CLEANUP COMPLETE		
Remedial Status 2:	NOT AVAILABLE		
<b>STATE LUST - State Leaking Underground Storage Tank / SRC# 4113</b>		EPA/Agency ID:	N/A
Agency Address:	SEA-TAC CRAWFORD AVIATION SEA-TAC INTERNATIONAL AIRPORT SEATAC, WA 98168-0727		
Tank Status:	NOT AVAILABLE		
Discovery Date:	JUNE 22, 1993		
Media Affected:	SOIL/LAND/SAND		
Substance:	NOT AVAILABLE		
Remedial Action:	NOT AVAILABLE		
Remedial Status 1:	CLEANUP IN PROGRESS/REQUIRED		
Remedial Status 2:	NOT AVAILABLE		
VISTA Address*:	<b>AMERICAN AVIONICS 7031 PERIMTER ROAD S. SEATTLE, WA 98108</b>	VISTA ID#:	7044967
<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #69

# UNMAPPED SITES CONT.

Description:	WASTE:TOTAL PETROLEUM HYDROCARBONS
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:95-02


VISTA Address*:	CITY OF SEATTLE/UNION PACIFIC RR RIGHT- 7500 BLOCK OF E. MARGINAL WAY SEATTLE, WA 98108	VISTA ID#:	6808441
-----------------	--	------------	---------

WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:TOTAL PETROLEUM HYDROCARBONS		
Description:	DATE ECOLOGY RECEIVED REPORT:9/21/93 0:00:00		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:93-12		

VISTA Address*:	CHEVRON STATION # 9-5257 8808 271ST ST NW SEATTLE, WA 98111	VISTA ID#:	5027907
-----------------	---	------------	---------

STATE LUST - State Leaking Underground Storage Tank / SRC# 2761		Agency ID:	2294
Agency Address:	CHEVRON STATION # 9-5257 8808 271ST ST NW SNOHOMISH, WA 98111		
Tank Status:	NOT AVAILABLE		
Discovery Date:	JUNE 11, 1991		
Media Affected:	GROUNDWATER,SOIL		
Substance:	NOT AVAILABLE		
Remedial Action:	NOT AVAILABLE		
Remedial Status 1:	CLEANUP IN PROGRESS/REQUIRED		
Remedial Status 2:	NOT AVAILABLE		

WA Toxics - Washington Toxics / SRC# 4061		EPA/Agency ID:	N/A
Agency Address:	CHEVRON #9-5257 8808 271ST ST. NW SNOHOMISH, WA 98111		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:8/15/94 0:00:00		
Description:	MEDIA:GROUNDWATER		
Description:	MEDIA:SOIL		
Description:	REPORT TYPE:INTERIM		
Description:	ISSUE OF SITE REGISTER:93-35		
Description:	WASTE:PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT:8/2/95 0:00:00		
Description:	MEDIA:GROUNDWATER		



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Version 2.5

Date of Report: January 2, 1998

Page #70

# UNMAPPED SITES CONT.

Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:94-13
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:3/17/94 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:93-23
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:6/11/91 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	ISSUE OF SITE REGISTER:91-31
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:12/19/91 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:92-14
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:2/27/92 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:92-19
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:3/20/92 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:92-20
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:4/28/92 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:92-25
Description:	WASTE:PETROLEUM PRODUCT
Description:	DATE ECOLOGY RECEIVED REPORT:2/11/93 0:00:00
Description:	MEDIA:GROUNDWATER
Description:	MEDIA:SOIL
Description:	REPORT TYPE:INTERIM
Description:	ISSUE OF SITE REGISTER:92-46



\*VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001


Date of Report: January 2, 1998

Version 2.5

Page #71

**UNMAPPED SITES CONT.**

VISTA Address*:	<b>MOBIL STATION - HAYES BROTHERS</b> <b>101 S. 111TH ST.</b> <b>SEATTLE, WA 98138</b>	VISTA ID#:	6808057
<b>WA Toxics - Washington Toxics / SRC# 4061</b>		EPA/Agency ID:	N/A
Agency Address:	MOBIL STATION - HAYES BROTHERS 101 S. 111TH ST. MOUNT VERNON, WA 98138		
Region:	NORTHWEST		
State Detail Description:	NO		
Contact:	NOT REPORTED		
Description:	WASTE: PETROLEUM PRODUCT		
Description:	DATE ECOLOGY RECEIVED REPORT: 12/24/91 0:00:00		
Description:	MEDIA: SOIL		
Description:	REPORT TYPE: FINAL		
Description:	ISSUE OF SITE REGISTER: 92-16		



**\* VISTA address includes enhanced city and ZIP.**

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Date of Report: January 2, 1998

Version 2.5

Page #72

# SITE ASSESSMENT REPORT

## DESCRIPTION OF DATABASES SEARCHED

### A) DATABASES SEARCHED TO 1 MILE

**NPL**  
**SRC#: 3622** VISTA conducts a database search to identify all sites within 1 mile of your property.  
The agency release date for NPL was September, 1997.

The National Priorities List (NPL) is the EPA's database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system score, be chosen as a state's top priority site, or meet three specific criteria set jointly by the US Dept of Health and Human Services and the US EPA in order to become an NPL site.

**SPL**  
**SRC#: 4060** VISTA conducts a database search to identify all sites within 1 mile of your property.  
The agency release date for Confirmed Contaminated Sites Report was June, 1997.

This database is provided by the Department of Ecology, Toxics Cleanup Program. The agency may be contacted at: 360-407-7200.

**SCL**  
**SRC#: 4059** VISTA conducts a database search to identify all sites within 1 mile of your property.  
The agency release date for Suspected Contaminated Sites Report was June, 1997.

This database is provided by the Department of Ecology, Toxics Cleanup Program. The agency may be contacted at: 360-407-7200.

The Washington Affected Media and Contaminants Report includes sites in the following categories: (1) National Priorities List (NPL) Sites, Federal Lead; (2) National Priorities List (NPL) Sites, State Lead; (3) State Sites, Confirmed Hazardous Substances Sites (sites where the presence of hazardous substances has been confirmed by laboratory or field determinations; (4) Potential Hazardous Substance Sites, these sites have been reported to the Department of Ecology and further investigation including sampling is underway; (5) State Sites Under- going Long-Term Monitoring; and (6) Sites For Which Cleanup is Complete. This report includes some leaking underground storage tank sites.


**CORRACTS**  
**SRC#: 3946** VISTA conducts a database search to identify all sites within 1 mile of your property.  
The agency release date for HWDMs/RCRIS was August, 1997.

The EPA maintains this database of RCRA facilities which are undergoing "corrective action". A "corrective action order" is issued pursuant to RCRA Section 3008 (h) when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. Corrective actions may be required beyond the facility's boundary and can be required regardless of when the release occurred, even if it predates RCRA.

### B) DATABASES SEARCHED TO 1/2 MILE

**CERCLIS**  
**SRC#: 3859** VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for CERCLIS was July, 1997.

The CERCLIS List contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL. The information on each site includes a history of all pre-remedial, remedial, removal and community relations activities or events at the site, financial funding information for the events, and unrestricted enforcement activities.



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 153929-001

Version 2.5

Date of Report: January 2, 1998

Page #73



**NFRAP  
SRC#: 3860**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for CERCLIS-NFRAP was July, 1997.

NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly, or the contamination was not serious enough to require Federal Superfund action or NPL consideration.

**RCRA-TSD  
SRC#: 3946**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for HWDMS/RCRIS was August, 1997.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA TSDs are facilities which treat, store and/or dispose of hazardous waste.

**SWLF  
SRC#: 2763**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for Municipal Sludge Waste Facilities was November, 1993.

This database is provided by the Department of Ecology, Solid Waste Services Program. The agency may be contacted at: .

**SWLF  
SRC#: 2764**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for Municipal Solid Waste Facilities was December, 1995.

This database is provided by the Department of Ecology, Solid Waste Services Program. The agency may be contacted at: 360-407-6133.

The Washington Solid Waste Inventory does not provide facility locations.

**LUST  
SRC#: 2761**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for Northwest Region Leaking Underground Storage Tank Site List was November, 1995.

This database is provided by the Department of Ecology, Northwest Regional Office. The agency may be contacted at: .

**LUST  
SRC#: 4113**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for Leaking Underground Storage Tank List was September, 1997.

This database is provided by the Department of Ecology, Toxics Cleanup Program. The agency may be contacted at: 360-4077179 .


The Washington Department of Ecology Leaking Underground Storage Tank List contains some of the same sites included on the Regional lists. This list is being used because there are some "new" sites and it includes a site identification number. Because two lists are being used, sites may be reporting twice.

**WA Site  
Register  
SRC#: 4061**

VISTA conducts a database search to identify all sites within 1/2 mile of your property.  
The agency release date for Toxic Cleanup Program Site Register was September, 1997.

This database is provided by the Department of Ecology, Toxics Cleanup Program. The agency may be contacted at: 360-407-7200.

The Washington Site Register Toxics Cleanup Program report details activities related to the study and cleanup of hazardous waste sites under the Model Toxics Control Act. Note that the State of Washington cautions that information contained under the Site Description is summarized information from an Independent Report and the Department of Ecology is not responsible for the accuracy of these reports. This report includes some leaking underground storage tank sites.



### C) DATABASES SEARCHED TO 1/4 MILE

UST's  
SRC#: 4114

VISTA conducts a database search to identify all sites within 1/4 mile of your property.  
The agency release date for Underground Storage Tank Database was September, 1997.

This database is provided by the Department of Ecology, Solid Hazardous Waste Program.  
The agency may be contacted at: 360-407-7179; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

### D) DATABASES SEARCHED TO 1/8 MILE

ERNS  
SRC#: 4144

VISTA conducts a database search to identify all sites within 1/8 mile of your property.  
The agency release date for was September, 1997.

The Emergency Response Notification System (ERNS) is a national database used to collect information on reported releases of oil and hazardous substances. The database contains information from spill reports made to federal authorities including the EPA, the US Coast Guard, the National Response Center and the Department of transportation. A search of the database records for the period October 1986 through July 1997 revealed information regarding reported spills of oil or hazardous substances in the stated area.

RCRA-LgGen  
SRC#: 3946

VISTA conducts a database search to identify all sites within 1/8 mile of your property.  
The agency release date for HWDMS/RCRIS was August, 1997.


The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Large Generators are facilities which generate at least 1000 kg./month of non-acutely hazardous waste ( or 1 kg./month of acutely hazardous waste).

RCRA-SmGen  
SRC#: 3946

VISTA conducts a database search to identify all sites within 1/8 mile of your property.  
The agency release date for HWDMS/RCRIS was August, 1997.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Small and Very Small generators are facilities which generate less than 1000 kg./month of non-acutely hazardous waste.

End of Report.



## APPENDIX D: QUALIFICATIONS OF ENVIRONMENTAL PROFESSIONAL CONDUCTING THIS ASSESSMENT

**Name**        **WARREN G. HANSEN, PE**

**Company**    **ONSITE ENTERPRISES, INC.**

**Title**        **President**

**Education**   B.S., Biology, University of Puget Sound, 1974  
                  M.S., Environmental Engineering, University of Florida, 1976

**Registration** Professional Civil Engineer, Washington (No. 21825) 1984  
                  Professional Civil Engineer, Montana (No. 8654PE) 1986  
                  Professional Civil/Environmental Engineer, Oregon (No. 16,255) 1992/1995  
                  Certified California Environmental Assessor, 1988

### **Select Experience:**

Mr. Hansen is a professional civil and environmental engineer specializing in hazardous and industrial waste management projects. During the last nineteen years he has provided technical leadership on a number of projects involving industrial surveys, spill prevention measures, site investigations and groundwater evaluations, remedial design, feasibility analyses, cost estimation, and facility design.

In the field of hazardous waste site remediation, Mr. Hansen has designed and conducted site investigations at wood-treating facilities, old coal gasification sites, transformer salvage yards, and smelter sites. His successful management skills stem from his ability to provide technical leadership in all phases of site analysis, from initial investigation to remedial cost and design.

Mr. Hansen is currently providing environmental management consultant services for the Port of Seattle's Southwest Harbor Project. Mr. Hansen is assisting the Port's engineering and environmental groups to manage and oversee four consultant teams tasked with investigating and remediating properties for marine terminal expansion. Current and historical site uses include a wood treating facility, shipyard, steel mill and municipal refuse landfill. Work on the Port of Seattle's Southwest Harbor Project has included property assessments of a variety of small and large industrial properties slated for redevelopment. Smaller industrial activities include an aluminum foundry, automotive body shop, chemical repackager, crating company and others. As technical reviewers for the Port's internal environmental staff, Mr. Hansen has gained excellent experience regarding the approaches, investigation costs, schedules and other pertinent aspects involved with these assessments.

Mr. Hansen has conducted and supported a number of industrial property investigations and assessments. For HDR Engineering, Inc., Mr. Hansen planned and helped perform Phase I environmental audits for two major northwest industrial parks in Eastern Washington encompassing more than 500 acres and including over 100 individual industrial and commercial tenants. Work included inspection of current tenant industrial activities, observations of waste management practices, and developing recommendations.

## **APPENDIX D, CONTINUED**

Mr. Hansen provided remedial engineering expertise for PTI Environmental Services and the Oregon Department of Environmental Quality to prepare the feasibility study and preliminary remedial design for the McCormick & Baxter wood-treating facility in Portland Oregon. Work included identification and development remedial measures for contaminated soil and nearshore river sediment. Contaminants of concern include metals, creosote and pentachlorophenol. Examined treatment/disposal alternatives and costs for soil and sediment contaminated with metals, creosote and other wood preservatives.

Performed a Phase I Environmental Site Assessment for Armored Transport Inc. for properties in the vicinity of East Yesler Way in Seattle, Washington. The assessment was performed to evaluate potential environmental issues related to properties considered for acquisition. A report describing the site, current and past uses, potential and existing environmental concerns and other information from a site reconnaissance and records investigation was prepared and provided the client.

Performed cost analyses of monitoring and disposal options for contaminated dredged materials from three regions in Puget Sound. Disposal alternatives included open water unconfined, open water confined, near shore, and upland. The analysis included the costs of dredging and transport, disposal, and material sampling and testing. The work supported the US Army Corps of Engineers contribution to the Puget Sound Dredged Disposal Analysis (PSDDA).

Served as Program Manager for miscellaneous environmental projects for a major timber company. Projects have addressed residual contaminants from mill decommissioning, underground tanks; TSCA compliance, and development/implementation of cleanup actions for PCBs and TPH-contaminated soil. Remedial methods have included excavation, in-place capping, and bioremediation of petroleum-contaminated soil.

Managed a site investigation of surface and subsurface soil contamination at a former metal scrap yard at the Port of Grays Harbor in Aberdeen, Washington. Recommended remedial measures (selective removal and capping) and presented measures to the Department of Ecology for approval.

Provided technical engineering services for site characterization and an RI/FS at a former scrap metal facility in Charlotte, North Carolina. Site soils contained PCBs, PAH compounds and lead; requiring innovative approaches for remediation. Site remediation included on-site groundwater and product extraction.

### **Publications**

Mr. Hansen has over two-dozen publications in the environmental sciences and engineering field.

### **Professional Affiliations**

Hazardous Materials Control Research Institute  
US EPA Traineeship (1975) under the Clean Water Act  
New Jersey Institute of Technology - Special recognition for  
contributions in the field of hazardous and toxic wastes management.